



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 15.01.2021
Emailed : 02.02.2021, 3.20pm
Date Survey : 18.01.2021

VEHICLE NO : SLG 811 Y
MODEL : MIT OUTLANDER 2.0
WIP : 61959

Material	:	\$	<u>10,813.88</u>
Labour	:	\$	<u>5,190.00</u>
Sub-Total	:	\$	<u>16,003.88</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>15,703.88</u>
GST 7%	:	\$	<u>1,099.27</u>
Grand Total	:	\$	<u>16,803.15</u>
Finalise By/Date	:	<u>LOI / 02/02/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Waiting surveyor
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/01/2021	Cust No/Name	KCV10755/LEE LAI WEI
	Reg No/Reg Date	SLG811Y / 20/03/2019
	Date In/Mileage	18/01/2021/ 33207
	Chassis/Package	GF7W0600602 /DC17P(F)
	Engine No	4J11AC3741
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	02/02/2021/ 15:05	BLC	260 / AiTing	61959			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								✓ 2250.00
REPLACE DAMAGED PARTS, REPLACE FRONT SUPPORT PANEL, FRONT BUMPER, FRONT BONNET, RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR, LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 100.00
E PNT88000								✓ 80.00
REMOVE AND INSTALL RADIATOR AND A/COND CONDENSER TO FACILITATE REPAIR								✓ 2450.00
A 55900099								✓ 40.00
TOP UP A/COND GAS AND CHECK A/COND SYSTEM								✓ 30.00
E PNT98000								✓ 40.00
RESPRAY ON FRONT SUPPORT PANEL, FRONT BONNET, RH FRONT DOOR, RH FRONT FENDER, LH FRONT DOOR, LH FRONT FENDER, FRONT BUMPER, AND ALL OTHER AFFECTED PORTIONS TO THE SAME								✓ 120.00
M SUNDRY								✓ 30.00
APPLY BODY SEALANT ON AFFECTED AREAS								✓ 50.00
A 54900099								-300.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
M SUNDRY								
PERFORM RUST PREVENTION ON AFFECTED AREAS								
A 10028901								
CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								
M SUNDRY								
SUNDRIES								
S SPECIALISTJOB								
SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME								
X EXC								
EXCESS FOR OWN DAMAGE CLAIM					1.00	✓ 58.00	23.00	44.66
X PNL,HEADLAMP SUPT,UPR RH					1.00	✓ 182.00	23.00	140.14
X PANEL,HEADLAMP SUPPORT,UPR					1.00	✓ 58.00	23.00	44.66
X PNL,HEADLAMP SUPT,UPR LH					1.00	✓ 857.00	23.00	659.89
X CONDENSER ASSY,A/C REFRIGE					1.00	✓ 1091.00	23.00	840.07
X RADIATOR ASSY								

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/01/2021	<table> <tr><td>Cust No/Name</td><td>KCV10755/LEE LAI WEI</td></tr> <tr><td>Reg No/Reg Date</td><td>SLG811Y / 20/03/2019</td></tr> <tr><td>Date In/Mileage</td><td>18/01/2021/ 33207</td></tr> <tr><td>Chassis/Package</td><td>GF7W0600602 /DC17P(F)</td></tr> <tr><td>Engine No</td><td>4J11AC3741</td></tr> <tr><td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 MODERN(995)</td></tr> <tr><td>Colour/Trim</td><td>D01 COSMIC BLUE MET/ BK BLACK</td></tr> </table>	Cust No/Name	KCV10755/LEE LAI WEI	Reg No/Reg Date	SLG811Y / 20/03/2019	Date In/Mileage	18/01/2021/ 33207	Chassis/Package	GF7W0600602 /DC17P(F)	Engine No	4J11AC3741	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK
Cust No/Name	KCV10755/LEE LAI WEI														
Reg No/Reg Date	SLG811Y / 20/03/2019														
Date In/Mileage	18/01/2021/ 33207														
Chassis/Package	GF7W0600602 /DC17P(F)														
Engine No	4J11AC3741														
Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)														
Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	02/02/2021/ 15:05	BLC	260 / AiTing	61959			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X LLC 4L					1.00	✓ 26.00	23.00	20.02
X FAN,COOLING,LH					1.00	✓ 78.00	23.00	60.06
X MOTOR,COOLING FAN,LH(120W)					1.00	✓ 479.00	23.00	368.83
X COVER,HEADLAMP SUPT PANEL					1.00	✓ 50.00	23.00	38.50
X CLIP,RR BUMPER					10.00	✓ 3.00	23.00	23.10
X GRILLE ASSY,RADIATOR					1.00	✓ 548.00	23.00	421.96
X HEADLAMP ASSY,LH					1.00	✓ 1938.00	23.00	1492.26
X HEADLAMP ASSY,RH					1.00	✓ 1938.00	23.00	1492.26
X HOOD					1.00	✓ 975.00	23.00	750.75
X INSULATOR,HOOD					1.00	✓ 133.00	23.00	102.41
X CLIP,HOOD INSULATOR					8.00	✓ 3.00	23.00	18.48
X ENGINE HOOD EMBLEM					1.00	✓ 80.00	23.00	61.60
X BRACKET,FR BUMPER SIDE,LH					1.00	✓ 18.00	23.00	13.86
X BRACKET,FR BUMPER SIDE,RH					1.00	✓ 18.00	23.00	13.86
X FACE,FR BUMPER					1.00	✓ 859.00	23.00	661.43
X COVER,FR BUMPER					1.00	✓ 359.00	23.00	276.43
X EXTENSION,FR BUMPER					1.00	✓ 515.00	23.00	396.55
X GARNISH,FR BUMPER,RH					1.00	✓ 48.00	23.00	36.96
X CLIP,ENG ROOM COVER					10.00	✓ 2.00	23.00	15.40
X LH GARNISH,FR BUMPER SIDE					1.00	✓ 220.00	23.00	169.40
X RH GARNISH,FR BUMPER SIDE					1.00	✓ 220.00	23.00	169.40
X LH GARNISH,FR BUMPER SIDE					1.00	✓ 112.00	23.00	86.24
X RH GARNISH,FR BUMPER SIDE					1.00	✓ 112.00	23.00	86.24
X REINF,FR BUMPER SIDE,RH					1.00	✓ 69.00	23.00	53.13
X REINF,FR BUMPER SIDE,LH					1.00	✓ 60.00	23.00	46.20
X REINFORCEMENT,FR BUMPER					1.00	✓ 134.00	23.00	103.18
X REINFORCEMENT,FR BUMPER					1.00	✓ 490.00	23.00	377.30
X GARNISH,FR LICENSE PLATE					1.00	✓ 23.00	23.00	17.71
X FENDER,FR RH					1.00	✓ 688.00	23.00	529.76
X FENDER,FR LH					1.00	✓ 688.00	23.00	529.76
X PANEL,HEADLAMP SUPPORT,LH					1.00	58.00	23.00	44.66
X PANEL,HEADLAMP SUPPORT,RH					1.00	58.00	23.00	44.66
X PIPE,A/C CONDENSER OUTLET					1.00	262.00	23.00	201.74

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/01/2021	<table> <tr><td>Cust No/Name</td><td>KCV10755/LEE LAI WEI</td></tr> <tr><td>Reg No/Reg Date</td><td>SLG811Y / 20/03/2019</td></tr> <tr><td>Date In/Mileage</td><td>18/01/2021/ 33207</td></tr> <tr><td>Chassis/Package</td><td>GF7W0600602 /DC17P(F)</td></tr> <tr><td>Engine No</td><td>4J11AC3741</td></tr> <tr><td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 MODERN(995)</td></tr> <tr><td>Colour/Trim</td><td>DO1 COSMIC BLUE MET/ BK BLACK</td></tr> </table>	Cust No/Name	KCV10755/LEE LAI WEI	Reg No/Reg Date	SLG811Y / 20/03/2019	Date In/Mileage	18/01/2021/ 33207	Chassis/Package	GF7W0600602 /DC17P(F)	Engine No	4J11AC3741	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)	Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK
Cust No/Name	KCV10755/LEE LAI WEI														
Reg No/Reg Date	SLG811Y / 20/03/2019														
Date In/Mileage	18/01/2021/ 33207														
Chassis/Package	GF7W0600602 /DC17P(F)														
Engine No	4J11AC3741														
Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)														
Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	02/02/2021/ 15:05	BLC	260 / AiTing	61959			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	INSULATOR,RDTR SUPPORT,UPR → Supp.				1.00	9.00	23.00	6.93
X	LATCH,HOOD				1.00	76.00	23.00	58.52
X	RIVET,FR BUMPER				1.00	5.00	23.00	3.85
X	MOULDING,FR WHEEL ARCH,LH				1.00	160.00	23.00	123.20
X	MOULDING,FR WHEEL ARCH,RH				1.00	160.00	23.00	123.20
X	DAMPER,HOOD				1.00	3.00	23.00	2.31
X	CLIP,RR BUMPER				10.00	3.00	23.00	23.10
X	RIVET,FR BUMPER				5.00	5.00	23.00	19.25
Z	TEXT							
	AIG OD CLAIM							
	DOA : 15.01.21							
	SURVEYOR STEVE LKK							
	POLICY NO: 1900067184							

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	10,813.88	Nett	15,703.88
Labour	5,030.00	7% GST on	1099.27
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	16,803.15
Diagnostics Job	0.00		
Sundry/Others	-190.00		
Total(w/o GST)	15,703.88		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SLG 811 Y**

<u>Materials</u>		<u>Cost (\$)</u>
1	Panel, headlamp support, LH	58.00
2	Panel, Headlamp support, RH	58.00
3	Pipe, A/C condenser outlet	262.00
4	Insulator, Rdtr Support, Up	9.00
5	Rivet, fr bumper	5.00
6	Moulding, Fr wheel Arch, LH	160.00
7	Moulding, Fr wheel Arch, RH	160.00
8	Damper, Hood	3.00
9	Clips (x10)	30.00
10	Rivet (x5)	25.00
Total		770.00
Less 23% discount		177.10
Total after discount		592.90
7% GST		41.50
Grand total		<u>\$ 634.40</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

21.08.17

offer to very emergency unit to check all the data
and then all the data

2021.01.26

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

to go Done

All DTCs

2021.01.26

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition	
	MPI/GDI/DIESEL	GAS_0E640000		No DTCs			
	Auto Stop & Go (AS&G)	ASG_25080000		No DTCs			
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs			
	AUTO CRUISE	GAS_0E640000		Non-target System			
	4WS/Electric Power Steering	EPS_45880040		No DTCs			
	ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs			
	SRS-AIR BAG	ORC_81047302		No DTCs			
	Air Conditioner	AC_80080011		No DTCs			
	ETACS	ETACS_83040801		No DTCs			
	Meter	MTR_84084001		No DTCs			
	Steering Angle Sensor	GS_SAS_47000100		Non-target System			
	AND	AND_8C080002		Non-equipped System or Communication Error			
	AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error			
	LIN	ETACS_83040801		Non-target System			
	Power Gate	ETG_92080000		Non-equipped System or Communication Error			

All DTCs

2021.01.26

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name			Malfunction Condition
	KOS/IMMO/Keyless	KOS_8A880020		No DTCs			
	OSS	OSS_9588000B		No DTCs			
	CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error			
	ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error			
	Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error			
	EPB	EPB_4C080000		No DTCs			
	Gateway	GW_C1000000		Non-equipped System or Communication Error			
	FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error			
	BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error			
	BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error			