TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510

Company Reg. No.: 200714616M GST Registration No.: 200714616M

Our Ref:

SMT 4116 P

Your ref:

SMQ 4593 K

18 January 2021

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909

Attn: Motor Claims Department

Dear Sir/Madam.

NAME OF CLAIMANT: FATIMAH BINTE MOHAMED ALI

VEHICLE NUMBER: SMT 4116 P

YOUR INSURED VEHICLE NUMBER: SMQ 4593 K

ACCIDENT ON 15 Jan 2021 ALONG PASIR RIS FLYOVER TWDS PASIR RIS DRIVE 8

AT ABOUT 06:40 HOURS

We refer to your email / fax dated 18 Jan 2021 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment LKK of Adrian Ling as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-17

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you! Appointed surveyor:

(Name & Signature):

Date & Time of Inspection:

Twincar Automotive Pte Ltd