

REPAIR ESTIMATE

Time: 13:08:41

Page: 1 13 TC

Arg Asia
cp/p)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305448713
 REGN NO : SHC2945A
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 06.08.2019
 DATE/TIME IN : 17.01.2021 15:45
 ACCIDENT DATE : 17.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	an
0002	04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00	an
0003	04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00	Ry
0004	04-01-0104-2370-G	REAR BUMPER FOGLAMP	1	201.50	20.00	161.20	an
0005	04-01-0104-2288-G	REAR BUMPER BEAM	1	394.80	20.00	315.84	X
0006	04-01-0104-3819-G	REAR BUMPER STAY LH	1	138.10	20.00	110.48	X
0007	04-01-0104-3919-G	REAR BUMPER STAY RH	1	138.10	20.00	110.48	X
0008	04-01-0104-2540-G	REAR FLOOR UNDER COVER	1	108.00	20.00	86.40	X
0009	04-01-0104-2544-G	REAR BUMPER TOW COVER	1	98.80	20.00	79.04	X
0010	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	rel
0011	09-01-0104-2133-G	REAR ANTENNA-SMARTKEY	1	40.50	20.00	32.40	X un.
0012	09-01-9999-0068-A	REVERSE SENSOR	1	180.00	2.00	180.00	an
0013	04-01-0104-2270-G	BOOTLID EMBLEM-HYBRID	1	24.30	20.00	19.44	an

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Ang Asia

Date: 18.01.2021

Time: 13:08:41

Page: 2

13 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305448713
 REGN NO : SHC2945A
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 06.08.2019
 DATE/TIME IN : 17.01.2021 15:45
 ACCIDENT DATE : 17.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0104-2271-G	BOOTLID EMBLEM-IONIQ	/ 1	31.30	20.00	25.04	new
0015 28-01-0103-0005-A	BOOTLID COMFORTDELGRO	/ 1	30.00	2.00	30.00	new
0016 28-01-0103-0006-A	BOOTLID 65521111	/ 1	30.00	0.20	30.00	new
0017 28-01-9999-2025-A	BOOTLID APPS	/ 1	40.00	0.02	40.00	new
0018 FNPS	NO PLATE(S)W/TRIM COVER	/ 1 N	55.00	0.00	55.00	new

1189.75
 20% - 951.80
 8% - 335
 1286.80

SUB-TOTAL : 2,145.44

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT-BOOTLID ETC	600.00	500
0002 L	R/I REVERSE SENSOR	120.00	30
			880
		SUB-TOTAL : 1,120.00	

1286.80
 880

\$2166.80

2days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: