



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
OPTIMA WERKZ PTE LTD (HQ) *			Ref:	CS/TP21000878/Kqd3e2
6 KUNG CHONG ROADSINGAPORE 159143			Date:	24/02/2021
ON BEHALF OF 1NSPIRED AUTO LEASING PTE LTD			Code:	TP426
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		SMN 6647S
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		14/01/2021
2. Vehicle Particulars & Condition				
Make & Model		HONDA FIT (A)	c.c	1496
Engine No.		HIDDEN	Year of Reg.	2019
Chassis No.		GP51344188	Colour	METALLIC PEARL WHITE
Odometer		-	Steering	IN ORDER
Brakes		IN ORDER	Modification	NIL
General		GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	SUNWIDE	8 mm
	L/H Front Tyre	185/60 R15	SUNWIDE	8 mm
	R/H Rear Tyre	185/60 R15	SUNWIDE	8 mm
	L/H Rear Tyre	185/60 R15	SUNWIDE	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/12/2020	Inspection Date	14/01/2021
	Survey held at	10 Ang Mo Kio Industrial Park 2A #01-05		
	Repairer	OPTIMA WERKZ PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	