



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LIM ZONG MIN, SHERMAN (LIN ZONGMIN)	Cust No/Name	/LIM ZONG MIN, SHERMAN (LIN ZONG
BLK 69 REDHILL CLOSE	Reg No/Reg Date	SML4845K / 23/05/201
#28-82	Date In/Mileage	/ 0
SINGAPORE 150069	Chassis No	KNAF3416MK5040936
Contact No Mobile: 97995892	Engine No	G4FGJH721702
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	16/01/2021/ 11:39	QUD	247 / DonBong	27530			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE,							1920.00
	REPAIR RH REAR FENDER DAMAGES							100.00
E PNT88000	REMOVE AND INSTALL PARKING ASSIST TO FACILITATE REPAIR WORK							1650.00
E PNT98000	PAINT WORK SPRAY RH REAR FENDER, REAR BUMPER AND							80.00
	AFFECTED PORTION							200.00
M SUNDRY	PERFORM RUST PREVENTION							280.00
A WHEELALIGNMENTBP	To Conduct Computerize Full Wheel Alignment							50.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							25.00
	USING HI-SCAN PRO TEST							31.00
M SUNDRY	SUNDRIES							181.00
M BRACKET ASSY-RR BPR SIDE UPR,L	X NAI	1.00	25.00	00.00				19.00
M BRACKET-ASSY RR BPR SIDE UPR,R	X NAI	1.00	31.00	00.00				4.00
M LAMP ASSY-SIDE T/SIGNAL,RH	X NAI	1.00	181.00	00.00				651.00
M COVER-RR BUMPER FOG LAMP,RH	CUT	1.00	19.00	00.00				241.00
M GROMMET ASSY-SCREW	MC	2.00	2.00	00.00				
M COVER-RR BUMPER	BR	1.00	651.00	00.00				
M COVER-RR BUMPER LWR	X NAI	1.00	241.00	00.00				

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: wcl

DATE: 5/2/21, 2.00pm

REMARKS: 3 days

Confirm & accepted by

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No lateral modification(s) is allowed

Authorized signatory and company stamp

7% GST on Net 5,432.00 380.24
Total Payable 5,812.24

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.