



YEOW KOON AUTO CARE PTE LTD

Blk 3012 Bedok Industrial Park E #01-2016, 2042, 2048 Singapore 489978

Tel: 64452200 / 93301273 Fax: 64482086 ROC 201-1161798

Email: yeowkoonautoare@gmail.com

Date: 20-1-21 Vehicle No: GOG 6015H Model: Mitsubishi Canter

Vehicle Chassis No:

FEA01BA20645

Quotation for cost of repair

S/n	Item	SN	SSgd	
1	01 set Rear Sensor	SN	\$180.00	cm
2	01 pc Rear Lamp with bulbs	SN	\$130.00	cm
3	01 set Rear Lamp Bracket	SN	\$150.00	pc
4	01 Panel Beating		\$250.00	200.
5	01 Spray painting		\$200	100.
6				
7	Tampah 97475349 / 67418434			
8	wp: 20/1/21 @ 245pm			\$760
9	Resurvey after repair			4/5 \$600
10	2 days			2 days
11	Tampah 97475349 / 67418434			
12	LKK Auto Consultants hence notify the Repairer of the following:			
13	• To resurvey before/after spray painting			
14	• To display damaged part(s) during resurvey			
15	• Parts prices are subject to confirmation			
16	• Third party survey is on a "Without Prejudice" basis			
17	• No illegal modification(s) is allowed			
18	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
19	Acknowledged by Repairer			
20	Signature:			
21	Date:			
TOTAL BEFORE GST:			\$1010.00	\$760
7% GST			\$70.70	\$53.20
TOTAL AFTER GST:			\$1080.70	\$813.20

Quotation by

Confirmed & agreeable by

YEOW KOON AUTO CARE PTE LTD

3rd party surveyor representative

Name

NRIC