

ASS. REC. BY:

REF:

CC3/A1621000918/RIVF3

259m

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMV 2418X

at Workshop m/s PREMIUM

of 21, Bannockburn

Insured:

Policy No. 2070137233

Claims No. 6953651638 SG

Sum Insured: _____ Excess: 0

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 357K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMV 2418X Yr Regn: 2020 / SEP

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A8 3.0 TFSI Quattro c.c. 2995

Colour: BLACK

A/C: Insured / Std / NI / NA

Sp. Reading: 7339

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAM 222F13K0043757

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Interd / Jammed / Leaked / Burnt or

Brake: Interd / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285/45R21

R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or: Hankook

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 15/01/2021

D.O.I. 19/01/2021

Survey held at PREMIUM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair Int - 240K
16/11/21	Final lg \$34,926.80 confirmed by email (Ref 38,043.00, 529)

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2) 25/5/21-Typist

Days Of Repair: 12

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format: Merimen

Lump Sum / L.S. \$34,926.80

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/01/2021 12:16 (SGT)
Date of Accident	15/01/2021 17:16 (SGT)
Exact Location of Accident	Near 8 Allamanda Grove, Singapore 269966
Additional Location Information	ALLAMANDA GROVE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMV2418X
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	JADA MARINE TRADE & CONSULTANT
Company Reg No	2XXXXX259M
Email Address	QIANJING@JADAMARINE.SG
Mobile Phone No	(Phone) +65-86133948
Alternative Phone No	+65-86133948

VEHICLE PARTICULARS

Manufacturer	Audi
Model	Q8
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070137233
Cover Note Number	-

DRIVER

Name of Driver	LEI FANG
NRIC No	SXXXX285G
Date Of Birth	20/02/1976
Occupation	Indoor

Date Of Driving Pass	04/10/2011
Driving experience	9 YEARS AND 3 MONTHS
Gender	Female
Mobile Number	(Phone) +65-86133948
Alt. Phone Number	-
Email Address	QIANJING@JADAMARINE.SG
Address	9 LEEDON HEIGHTS
Address complement	#31-22
Postcode	267954
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Other
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING STRAIGHT ON MY LANE GOING UP-HILL. THE THIRD PARTY WAS AT THE OPPOSITE LANE. SHE CROSS ONTO MY LANE AND COLLIDED INTO MY VEHICLE

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR5341X
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-

Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE


1. Please report promptly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind the policy.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reports may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers to the GIC Records Management Centre (operated by the General Insurance Association of Singapore (GIA)) for archiving and the copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if requested.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data (personal information set out in the Form) and any other personal information provided to me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers (who have insured vehicles) involved in this accident (all insurers) (who have insured vehicles) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' law/insure law firm, the Ministry of Transport of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes").
- (a) all insurers (who have insured vehicles) involved in this accident and the Insurers' law/insure law firm, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law/insure law firm), which may be able outside of Singapore, for use or more of the above Purposes.

Policyholder's Signature / Date & Time: Letter 19 Nov

Driver's Signature (Driver is not the policyholder) / Date & Time: Letter 19 Nov

Witnessed by Reporting Officer / Personnel: Letter 19 Nov

Sketch Plan



Describe Circumstances of the Accident

I was driving through a red light when a car came from the side and hit me. The car was at the red light and I was going straight. The car hit me from the side and I was thrown into the air.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



Work Order: 888888
VIN: WAUZZZF13KD043757
Technician: way
License: SMV2418X
Odometer: 7352
Date: 21.1.21 10:18

Audi : Q8 : Air Suspension (1BK) : 2018- (4MN)
18-


Current Measurements



* One or more values are not within specification. Tire wear, handling and safety problems may result.

Order: 11792/2
WAUZZZF1KD043757
Technician: WAY
Vehicle: SMV2418X
Meter: 7353
1.2.21 13:02

Audi : Q8 : Air Suspension (1BK) : 2018- (4MN)
18-



• One or more values are not within specification. Tire wear, handling and safety problems may result.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0056/2021/NS
DATE : 18-Jan-21
WIP : 11792

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : JADA MARINE TRADE & CONSULTANT
ADDRESS : 5 SOON LEE STREET
#04-28
SINGAPORE 627607
TELEPHONE : HP +65 86133948
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070137233
VEHICLE NO : **SMV 2418 X**
MODEL CODE : AUDI Q8 3.0 TFSI QU 4MNOX
MODEL YEAR : 22/9/2020
ENGINE NO : DCB 127910
CHASSIS NO : WAUZZZF13KD043757
MILEAGE : 7352KM
DATE IN : 16-Jan-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Jan-21
PLACE OF ACCIDENT : ALLAMANDA GROVE

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2418 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	✓
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 ? ✓	✓
3	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00 300 ✓	✓
4	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00 ? pleh ✓	✓
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	@600 \$ 6,300.00 1200 3000 ✓	✓
SUB TOTAL LABOUR CHARGES		: \$ 11,030.00	

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2418 X**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER RHS, RHS FRONT FENDER, BONNET, HINGES, BOTH FRONT WHEEL ARCH TRIMS AND RHS FRONT DOOR. @ 600	\$ 5,800.00	2800 ✓
7	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT TEST.	S/N \$ 520.00	✓
8	TO TOW BACK VEHICLE FROMT ACCIDENT SCENE.	S/N \$ 280.00	X 12
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 17,822.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>de-</i>	\$	2,724.00	<i>2179.20</i>
2 FRONT BUMPER FIXING PARTS <i>? X 11</i>	\$	378.00	<i>X</i>
3 FRONT BUMPER CLOSING ELEMENT - RH <i>? cm</i>	\$	120.00	<i>95.60</i>
4 FRONT BUMPER FRAME - RH <i>? X su</i>	\$	82.00	<i>X</i>
5 FRONT BUMPER COVER - RH <i>? X su</i>	\$	82.00	<i>X</i>
6 FRONT BUMPER CLOSING ELEMENT - CENTRE <i>? X su</i>	\$	278.00	<i>X</i>
7 FRONT BUMPER TRIM - CENTRE <i>? X su</i>	\$	182.00	<i>X</i>
8 FRONT BUMPER GRILLE <i>? X su</i>	\$	206.00	<i>X</i>
9 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>? X su</i>	\$	210.00	<i>X</i>
10 FRONT BUMPER UNDERRUN BAR <i>? X su</i>	\$	807.00	<i>X</i>
11 FRONT SPOILER - RH <i>de-</i>	\$	211.00	<i>168.80</i>
12 FRONT BUMPER TRIM <i>? X su</i>	\$	245.00	<i>X</i>
13 FRONT BUMPER AIR GUIDE GRILLE - RH <i>su</i>	\$	183.00	<i>146.40</i>
14 ULTRASOUND SENSOR SUPPORT - LH/RH <i>? X su</i>	\$	58.00	<i>X</i>
15 RADIATOR GRILLE <i>X su</i>	\$	2,500.00	
16 RADIATOR GRILLE COVER - CENTRE <i>X su</i>	\$	72.00	
17 RADIATOR GRILLE COVER - LH/RH <i>X su</i>	\$	30.00	
18 FRONT BUMPER GUIDE SECTION - RH <i>? cm</i>	\$	44.00	<i>35.12</i>
19 FRONT BUMPER FOAM FILLER PIECE <i>? X su</i>	\$	171.00	<i>X</i>
20 FRONT BUMPER CARRIER <i>? X su</i>	\$	964.00	<i>X</i>
SUB TOTAL SPARE PARTS	:	\$	9,547.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT BUMPER BRACKET - RH ? Xsue		\$	34.00	X
22	FRONT BUMPER COVER 2 cut ✓		\$	131.00	104.40
23	CAUTION SIGN STICKER 2 X ny	NEC	\$	14.00	
24	AIRCON STICKER 2 X nn	NEC	\$	8.00	
25	FRONT PARKING AID SENSOR ? Xsue		\$	242.00	X
26	FRONT PARKING AID SEAL RING 2 X nn	4	\$	14.00	
27	FRONT FENDER - RH bt ✓		\$	2,310.00	1848
28	FRONT FENDER ATTACHMENT PARTS 2 X nn		\$	66.00	X
29	FRONT FENDER BRACE - RH ? bt ✓		\$	152.00	121.60
30	FRONT FENDER BRACKET - RH ? Xsue		\$	65.00	X
31	FRONT WHEEL HOUSING LINER - RH 2 Xsue		\$	249.00	X
32	REAR WHEEL HOUSING LINER - RH ? de ✓		\$	249.00	198.80
33	WHEEL HOUSING LINER ATTACHMENT PART 2 X nn		\$	73.00	X
34	FRONT SPOILER - RH ? Xsue		\$	68.00	X
35	HEADLAMP COVER - RH ? Xsue		\$	102.00	X
36	HEADLIGHT MOUNTING - RH ? cm ✓		\$	118.00	94.40
37	LED HEADLIGHT - RH 2 ✓		\$	12,792.00	10,233.60
38	LIFT CYLINDER - RH 2 Xsue		\$	198.00	X
39	FRONT WHEEL COVER 2 LH RH	2	\$	1,150.00	920
40	S-LINE INSCRIPTION 2 ✓		\$	128.00	102
SUB TOTAL SPARE PARTS		:	\$	18,163.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 BONNET <i>X nn</i>		\$ 4,978.00	
42 BONNET ATTACHMENT PARTS <i>X nn</i>		\$ 126.00	
43 BONNET LID HINGE - LH/RH <i>X nn</i>	2	\$ 344.00	
44 BONNET IMPACT PROTECTION - LH/RH <i>X nn</i>	2	\$ 90.00	
45 BONNET IMPACT PROTECTION - CENTRE <i>X nn</i>		\$ 30.00	
46 BONNET STRIKER - RH <i>X nn</i>		\$ 120.00	
47 BONNET LID LOCK <i>X nn</i>		\$ 214.00	
48 LOCK CARRIER <i>? ca</i>		\$ 1,218.00	<i>974.40</i>
49 RADIATOR AIR GUIDE - RH <i>? xsu</i>		\$ 42.00	<i>X</i>
50 CHARGE AIR COOLER <i>? bt</i>		\$ 1,002.00	<i>801.60</i>
51 CHARGE AIR COOLER AIR GUIDE <i>? ca</i>		\$ 89.00	<i>70.56</i>
52 READY MIX COOLANT <i>? ne</i>		\$ 179.00	<i>143.04</i>
53 FRONT ALUMINIUM RIM - RH <i>su</i>		\$ 3,552.00	<i>2841.60</i>
54 SUPPORT FRAME <i>? xsu</i>		\$ 3,846.00	<i>X</i>
55 FRONT WISHBONE LINK <i>? bt</i>		\$ 747.00	<i>597.20</i>
56 SUSPENSION GUIDE - RH FRONT <i>? bt</i>		\$ 703.00	<i>562</i>
57 FRONT UPPER CONTROL ARM - RH <i>? xsu</i> UPPER/LOWER	2	\$ 720.00	<i>X</i>
58 WHEEL BEARING HOUSING - RH <i>? bt</i>		\$ 811.00	<i>648.40</i>
59 SWIVEL JOINT <i>? bt</i>		\$ 216.00	<i>172.80</i>
60 WHEEL HUB <i>? bt</i>		\$ 479.00	<i>383.20</i>
SUB TOTAL SPARE PARTS	:	\$ 19,506.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
61 DOUBLE ANGLE BALL BEARING ? <i>neu</i> ✓	\$	254.00	<i>202.80</i>
62 SUSPENSION FORKS - RH ? <i>bt</i> ✓	\$	366.00	<i>292.40</i>
63 COUPLING ROD ? <i>xsu</i>	\$	127.00	<i>X</i>
64 ANTI-ROLL BAR ? <i>xsu</i>	\$	516.00	<i>X</i>
65 GAS STRUT ? <i>xsu</i>	\$	3,290.00	<i>X</i>
66 DRIVE SHAFT ? <i>xsu</i>	\$	2,480.00	<i>X</i>
67 FRONT SPEED SENSOR ? <i>xsu</i>	\$	110.00	<i>X</i>
68 TRACK ROD ? <i>bt</i> ✓	\$	134.00	<i>106.80</i>
69 TIE ROD END - RH ? <i>bt</i> ✓	\$	195.00	<i>156</i>
70 FRONT NO PLATE <i>Xsu</i>	S/N \$	60.00	
71 SUNDRIES ? <i>neu</i> ✓	\$	400.00	<i>34.08</i>
TOTAL SPARE PARTS	:	\$ 55,148.00	
TOTAL LABOUR CHARGES	:	\$ 17,822.00	
GRAND TOTAL	:	\$ 72,970.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Rosm - Hp 90010078*
SURVEYED DATE : *19/01/2021 @ 1120*
AUTHORISED DATE :
EXCESS COST : *6 days*
LIABILITY :
REMARKS : *EXCESS: TBA*

*Reveal
Re-survey before paint*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- Subject to final approval from Insurance Company

Accepted by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2418 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	
3	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	300
4	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00	2.400.00 ? plus ?
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	@600 \$ 6,300.00	1200 + 1500 1800 3 days
SUB TOTAL LABOUR CHARGES		\$ 11,030.00	= 3000

* 3 hrs (additional)

Rahul
Ry
21/01/2021

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
41 BONNET X		\$	4,978.00	
42 BONNET ATTACHMENT PARTS X		\$	126.00	
43 BONNET LID HINGE - LH/RH X	2	\$	344.00	
44 BONNET IMPACT PROTECTION - LH/RH X	2	\$	90.00	
45 BONNET IMPACT PROTECTION - CENTRE X		\$	30.00	
46 BONNET STRIKER - RH X		\$	120.00	
47 BONNET LID LOCK X		\$	214.00	
48 LOCK CARRIER ? cm ✓		\$	1,218.00	
49 RADIATOR AIR GUIDE - RH ?		\$	42.00	
50 CHARGE AIR COOLER ? bt ✓		\$	1,002.00	
51 CHARGE AIR COOLER AIR GUIDE ? cm ✓		\$	89.00	
52 READY MIX COOLANT ? cm ✓		\$	179.00	
53 FRONT ALUMINIUM RIM - RH scm ✓		\$	3,552.00	
54 SUPPORT FRAME ?		\$	3,846.00	
55 FRONT WISHBONE LINK ? bt ✓		\$	747.00	
56 SUSPENSION GUIDE - RH FRONT ? bt ✓		\$	703.00	
57 FRONT UPPER CONTROL ARM - RH ? X UPPER/LOWER	2	\$	720.00	
58 WHEEL BEARING HOUSING - RH ? bt ✓		\$	811.00	
59 SWIVEL JOINT ? bt ✓		\$	216.00	
60 WHEEL HUB ? bt ✓		\$	479.00	
SUB TOTAL SPARE PARTS	:	\$	19,506.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
61 DOUBLE ANGLE BALL BEARING ? <i>ne</i> ✓		\$ 254.00	
62 SUSPENSION FORKS - RH ? <i>lt</i> ✓		\$ 366.00	
63 COUPLING ROD ?		\$ 127.00	
64 ANTI-ROLL BAR ?		\$ 516.00	
65 GAS STRUT ?		\$ 3,290.00	
66 DRIVE SHAFT ?		\$ 2,480.00	
67 FRONT SPEED SENSOR ?		\$ 110.00	
68 TRACK ROD ? <i>lt</i> ✓		\$ 134.00	
69 TIE ROD END - RH ? <i>lt</i> ✓		\$ 195.00	
70 FRONT NO PLATE X	S/N	\$ 60.00	
71 SUNDRIES ?		\$ 400.00	
TOTAL SPARE PARTS	:	\$ 55,148.00	
TOTAL LABOUR CHARGES	:	\$ 17,822.00	
GRAND TOTAL	:	\$ 72,970.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Add

Famy
31/03/21