



TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SJJ8005M**  
 MODEL : **TOYOTA VOXY**  
 DATE OF ACCIDENT : 19.01.21  
 TIME OF ACCIDENT : 08:50HRS

27	REAR END PANEL TOP GARNISH <i>Rehd</i>	1	\$ 158.60	\$ 158.60	✓
28	REAR FLOOR PANEL <i>Rejs</i>	1	\$ 698.70	\$ 698.70	+
29	REAR FLOOR PANEL TOP BOARD <i>crhd</i>	1	\$ 1,105.50	\$ 1,105.50	540
30	REAR FLOOR PANEL TOP BOARD INNER SUPPORT <i>new</i>	1	\$ 403.20	\$ 403.20	+
31	REAR FLOOR MAT <i>new</i>	1	\$ 421.60	\$ 421.60	+
32	REAR JACK COVER GARNISH <i>Rehd</i>	1	\$ 128.70	\$ 128.70	✓

8551.10 TOTAL PRICE \$ 16,367.71  
 6413.32 LESS 25% \$ 4,091.93  
**SUB TOTAL PRICE \$ 12,275.78**

**SPECIAL NETT ITEMS**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 80.00	\$ 80.00	50
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
4	TAILGATE OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	✓
5	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
6	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
7	TAILGATE WINDSCREEN INNER SEAL <i>Nec</i>	1	\$ 60.00	\$ 60.00	40
8	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
9	TAIL LAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	20
10	TAIL LAMP LOWER PANEL SEALANT <i>new</i>	2	\$ 60.00	\$ 120.00	+
11	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	60
12	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
13	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
14	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
15	REAR FLOOR MAT CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
16	REAR FLOOR INSULATION SEAL (SET) <i>new</i>	1	\$ 350.00	\$ 350.00	+
17	REAR JACK (SPECIAL TYPE) <i>new</i>	1	\$ 180.00	\$ 180.00	+
18	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	380
19	REVERSE SENSOR (2PCS) <i>new</i>	1	\$ 250.00	\$ 250.00	200

**TOTAL \$ 2,380.00** 970

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	1000

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SJJ8005M**  
 MODEL : **TOYOTA VOXY**  
 DATE OF ACCIDENT : 19.01.21  
 TIME OF ACCIDENT : 08:50HRS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1000
3	TUFF COAT	\$ 250.00	80
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	80
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	50
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
9	TRANFER TAILGATE MECHANISM	\$ 80.00	✓
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

**TOTAL**

\$ 5,320.00

2610

Adrian Lij  
L/S 20/01/21

TOTAL PARTS COST : \$ 14,655.78  
 TOTAL LABOUR COST : \$ 5,320.00  
 TOTAL REPAIR COST : \$ 19,975.78

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

OT Days

Total: 9993.32

L/S: 8Kc

81c

YOURS FAITHFULLY,

*MICHELLE*  
 SERVICE ADVISOR  
 MICHELLE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer