

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 885Y

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT DOOR RH (CONSISTENT) | BENT | 1,600.21 | 1,600.21 |
| 1 | FRONT DOOR RUBBER RH (CONSISTENT) | NOT NECESSARY | 319.35 | - |
| 1 | FRONT STEP GARNISH RH (CONSISTENT) | CUT | 165.80 | 165.80 |
| 1 | DOOR CENTRE PILLAR RH (CONSISTENT) | BENT | 598.60 | 598.60 |
| 1 | SIDE SLIDING DOOR RH (CONSISTENT) | TO REPAIR SEE LABOUR | 1,655.35 | - |
| | LESS 25% DISCOUNT | | -1,084.83 | -591.15 |
| | | | 3,254.48 | 1,773.46 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT DOOR LETTERING STICKER RH (SN) (CONSISTENT) | NECESSARY | 20.00 | 20.00 |
| 1 | FRONT WHEEL HUB CAP RH (SN) (CONSISTENT) | CUT | 120.00 | 120.00 |
| 1 | SIDE SLIDING DOOR GLASS SPONGE TAPE RH (SN) (CONSISTENT) | NOT NECESSARY | 20.00 | - |
| 1 | SIDE SLIDING DOOR GLASS SEALANT RH (SN) (CONSISTENT) | NOT NECESSARY | 60.00 | - |
| | | | 220.00 | 140.00 |
| | <u>LABOUR</u> | | | |
| | TO KNOCK OUT DENT ,CUT /WELD DOOR CENTRE PILLAR AND REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF SIDE SLIDING DOOR RH . | | 800.00 | 600.00 |
| | TO SPRAY PAINTING ON ACCIDENT PORTION . | | 800.00 | 600.00 |
| | TO REMOVE,REFIX CUSHION AND INNER TRIM . | | 120.00 | 60.00 |
| | TO REMOVE,REFIX SIDE SLIDING DOOR GLASS . | NOT NECESSARY | 120.00 | - |
| | 4 WHEEL ALIGNMENT . | | 80.00 | 80.00 |
| | TO TUFF KOTE. | | 90.00 | 30.00 |
| | | | 2,010.00 | 1,370.00 |
| | GRAND TOTAL | | 5,484.48 | 3,283.46 |

Report Ref No. CC4/ASM21000927/T1pa3q2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 2,600.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | · |

Report Ref No. CC4/ASM21000927/T1pa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

mont

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.