

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

SHA2847K

ESTIMATE

DATE : 19.01.2021
VEHICLE NO : GBH885Y
MAKE/MODEL : TOYOTA HIACE
ACC DATE : 02.01.2021

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
<u>LIST PRICE</u>			
1	1 FRONT DOOR RH	1,600.21	bt- 1,600.21
2	1 FRONT DOOR RUBBER RH	319.35	nn x 319.35
3	1 FRONT STEP GARNISH RH	165.80	int- 165.80
4	1 DOOR CENTRE PILLAR RH	598.60	bt- 598.60
5	1 SIDE SLIDING DOOR RH	1,655.35	Rx 1,655.35
		2364.61	4,339.31
		LESS 25%	1,084.83
		1773.45	3,254.48

SPECIAL NETTS ITEM

1	1 FRONT DOOR LETTERING STICKER RH	20.00	na- 20.00
2	1 FRONT WHEEL HUB CAP RH	120.00	int- 120.00
3	1 SIDE SLIDING DOOR GLASS SPONGE TAPE RH	20.00	nn x 20.00
4	1 SIDE SLIDING DOOR GLASS SEALANT RH	60.00	nn x 60.00
			140- 220.00

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD DOOR CENTRE PILLAR AND REPLACE ACCIDENT PARTS	600-	800.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	600-	800.00
3	TO REMOVE, REFIX CUSHION AND INNER TRIM	60	120.00
4	TO REMOVE, REFIX SIDE SLIDING DOOR GLASS	nn x	120.00
5	4 WHEEL ALIGNMENT	✓	80.00
6	TO TUFF KOTE	30-	90.00

3283.45

1370- 2,010.00

L/S 2600, 5 days

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 5,484.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

17495789 WP 19/1/21 @ 420pm
L/S Resurvey after repair.
farfikh @ lkhauto.com
05 days