
SV0L211J000E / VICOM LTD (VAC) - Kaki Bukit [415933] ENTRY DATE & TIME: 19/01/2021 16:03 (SGT) SUBMITTED BY: Stif Fablon Abdu Kader VERSION: 1 (19/01/2021 16:03 (SGT))



- IMPORTANT NOTICE

 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for Investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss	19/01/2021 11:00 (SGT) Singapore BUKIT TIMAH ROAD TWRDS SCOTTS ROAD
DETAILS	OF OWN VEHICLE
Vehicle Registration Number	SLN3200D
INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner Company Reg No Email Address Mobile Phone No Alternative Phone No	TAN CHEE HENG ALFRED (CHEN ZHIXING ALFRED) SXXXX188E alfredthc@singnet.com.sg (Phone) +65-83829966
VEHICLE PARTICULARS	
Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category	110112/17 0111 1:000 001
INSURANCE COMPANY	
Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number	NTUC Comprehensive No 5120233584
DRIVER	
Name of Driver Company Reg No Date Of Birth	TAN CHEE HENG ALFRED (CHEN ZHIXING ALFRED) SXXXX188E 04/10/1980

Indoor

Occupation

Date Of Driving Pass	24/10/2000					
Driving experience	20 YEARS AND 3 MONTHS					
Gender	Male					
Mobile Number	(Phone) +65-83829966					
Alt. Phone Number	+65-83829966					
Email Address						
	alfredthc@singnet.com.sg 10C HOUGANG STREET 11 #12-46 THE MINTON					
Address	TOC HOUGANG STREET TT#12-40 THE MINTON					
Address complement						
Postcode	534077					
Is the driver the policyholder?	Yes					
If No, Relationship of the Driver with the Insured	-					
Does Driver Own Other Vehicles?	No					
Vehicle Registration Number of Other Vehicle Owned by Driver						
Insurance Company of Other Vehicle Owned by Driver	<u>-</u>					
insurance company of Other Vehicle Owned by Driver	-					
GENERAL INFORMATION OF THE ACCIDENT						
SERVE IN ORIGINAL TREASURED						
Type of Accident	Collision - Head to Rear					
Weather Conditions	Clear					
Road Surface	Dry					
Security of the four to be the analysis of the contract of the						
OTHER INFORMATION						
Was any foreign vehicle involved in the accident?	No					
Number of vehicles involved in the accident	2					
Was anybody injured in the Accident?	No					
Was any injured conveyed to hospital by ambulance?						
Was any other material or property damaged?	No					
Number of Passengers (Including Driver)	1					
Has the driver been approached by unknown person(s)						
soliciting/offering accident claims assistance?	No					
DETAILS OF POLICE ACTION						
DETAILS OF POLICE ACTION						
Was the accident reported to the police?	No					
Was notice of intended Prosecution given?	No					
If yes, against whom?	=					
n yes, against mon.						
CIRCUMSTANCES OF ACCIDENT						
REFER ATTACHED;						
ATTACHMENT(S)						
and forested of all provided a lone agency, so are even, as a second of						
Are accident photos available for attachment?	Yes					
Was there any video captured by Car Camera?	No					
Was there any audio recorded?	No					

0/_	19.01	2021	at ab	out	llam.	1 Mat	floyell	110	along	Butit	Timah	Rad
h	Cerlle	01		Was	Stationary	11.	from	1 4	offic	Sudde	dk t	_
owards	Sotts	Kood	1	nai	Signorary	dur it) jiun	- "	dill C	200011		
Vehicle B	hit or	IUV	Yelricle	Α.				_			-	
didit.	111 01	- 14	lented	11.								
								_	_			
							7 19	-	4	_		
-			-				101 150	100	Hypox	1,17,46	NVI.	-
				7	1					-		
n-ce t				10.	97) 1.	AT A			-		1000	_
								_	_			
								_				
							1					
						day.		5				
										100		
							(4				
								-	-			_
- 114	1917		_	-55		-			_	_	_	
10.10				_		_				-		-
												_
												_
							1		- ii			
								11.1	1			
										2		
claration												
declare the	foregoing p	particular	are true i	every !	espect.					KAKIB		
0										ki Bukit / ingapore		
0				(X)				1	Tel: 674	16697	Fax: 67-	19230
A				CAH					Emal	i vackbe	vicom.co	mag
yholder's	nature / Do		Disade (1	(V driver is not			_				
yholders p	mature / Di		& Time	ynanuro	(a surer is not	une poscyt	noeder) / D	ulo	Person	ed by Rep	orting Cen	tre
										1	9 JAN	2021

SKETCH PLAN

report below made available aforesaid.

Company made or the Personal Bulla Protection Act (PDPA)
understand, acknowledge, agree and consent that:

John printer, and overhop and the Company bull protection of Signetons ("GIA") may be permitted to collect, use, disclose
another process my personal distalpersonal information set out in this (form) and any other personal information provided by my or
sourcessed by my instruct (collectively the "Personal Information and collection") and disclose and furnation such processes for the service (collectively information provided by my or
who have insured verticing) involved in this accident call resulting the processing of the service of the servi

e shove Ruposes.

IDAC KAKI BUKIT (VAC)
25 Kaki Bukit Ave 4 #02-02
5 Singapore 4 15935
Tel: 67416697 Fax: 67492505
Emall: vackbgrvicom.com.ag



19 JAN 2021

A) 81H 3200 D

B) 685 74189