

SWAGEN CENTRE SINGAPORE

Alexandra Road
 #01-159934
 Reg. No.: 199101494Z
 No.: M200985052



SKODA

Commercial Vehicles

Quotation

Non binding - Preview

Page

1/3

Company
 CHINA TAIPING INSURANCE (S) PL
 3 ANSON ROAD
 #18-00 SPRINGLEAF TOWER
 Singapore 079909

Customer Details:
 Mr
 EE
 JIAN WEN, JEREMY
 114 CLEMENTI STREET 13
 #02-63
 Singapore 120114

Document no.
 Document date 19-01-2021
 Customer no. 5211001170
 Customer GST-ID 200208384E
 Dealer 30001
 Job order number 2021002748/ 1
 Job order date 19-01-2021
 Service Advisor TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SFR198Y	5T13NZC1	28-06-2019	WVGZZZ1TZKW059334	Touran Comfortline EQP 1.4 TSI 110kW DSG	20,750

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
5TA827025P	Rear Trunk Lid	1	pcs.	2,207.90	#1	2,207.90	2,362.45
D 169300M2	1k Window Adhesive	2	pcs.	51.11	#1	102.22	109.38
D 00940104	All Purpose Cleaner	1	pcs.	94.03	#1	94.03	100.61
D 00920002	Primer	1	pcs.	27.39	#1	27.39	29.31
D 181802M1	Activator For Precoated W	1	pcs.	25.14	#1	25.14	26.90
D 00950025	Applicator	2	pcs.	10.12	#1	20.24	21.66
5TA827939 041	Spoiler Satin Black	1	pcs.	260.54	#1	260.54	278.78
	LHR W/SCREEN SIDE MLDG	1	pcs.				
5TA827940 041	Spoiler Satin Black	1	pcs.	272.52	#1	272.52	291.60
	RHR W/SCREEN SIDE MLDG	1	pcs.				
8D0853419D	Packing Adhesive	1	pcs.	29.20	#1	29.20	31.24
	REAR NUMBER PLATE PACKING	1	pcs.				
WHT007341	Rivetted Cap Nut	4	pcs.	2.28	#1	9.12	9.76
5TA827505D	Hood Latch	1	pcs.	158.42	#1	158.42	169.51
	LOCK	1	pcs.				
5TA827520 9B9	Cover Lock Satin Black	1	pcs.	19.79	#1	19.79	21.18
	LOCK COVER	1	pcs.				
5TA827705A	Gasket	1	pcs.	317.42	#1	317.42	339.64
	REAR WETHERSTRIP	1	pcs.				
5TA827566B	Pushbutton For Electric L	1	pcs.	1,470.77	#1	1,470.77	1,573.72
5NA943021	Led Licence Plate Light	2	pcs.	100.67	#1	201.34	215.43
3CN945087	Additional Brake Light W	1	pcs.	221.63	#1	221.63	237.14
	3RD BRAKELIGHT	1	pcs.				
5TA853630A DPJ	Vw Sign Black/Bright Chro	1	pcs.	105.72	#1	105.72	113.12
5TA853687 2ZZ	Inscription Bright Chrome	1	pcs.	72.44	#1	72.44	77.51
	EMBLEM - TOURAN	1	pcs.				
5TA807417 GRU	Cover For Bumper Primed	1	pcs.	1,321.12	#1	1,321.12	1,413.60
5TA807568A 9B9	Spoiler Satin Black	1	pcs.	323.75	#1	323.75	346.41
WHT005263	Rivet	4	pcs.	1.14	#1	4.56	4.88
5TA807305	Bumper	1	pcs.	544.33	#1	544.33	582.43
	REINFORCEMENT	1	pcs.				
5TA807863	Attachment Strip	1	pcs.	63.48	#1	63.48	67.92
	BUMPER CTR BRACKET	1	pcs.				
5TA807453	Guide Piece	1	pcs.	41.17	#1	41.17	44.05
	LHR BUMPER BRACKET (UPPER)	1	pcs.				
5TA807454	Guide Piece	1	pcs.	41.17	#1	41.17	44.05
	RHR BUMPER BRACKET (UPPER)	1	pcs.				
5TA807393	Guide Piece	1	pcs.	33.60	#1	33.60	35.95
	LHR BUMPER BRACKET (SIDE)	1	pcs.				
5TA807394	Guide Piece	1	pcs.	33.60	#1	33.60	35.95
	RHR BUMPER BRACKET (SIDE)	1	pcs.				
WHT005560	Speed Nut	6	pcs.	1.58	#1	9.48	10.14

SWAGEN CENTRE SINGAPORE

andra Road
ore 159934
eg. No.: 199101494Z
No.: M200985052



Quotation

Non binding - Preview

Page 2/3

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
EE
JIAN WEN, JEREMY
114 CLEMENTI STREET 13
#02-63
Singapore 120114

Document no.
Document date 19-01-2021
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2021002748/ 1
Job order date 19-01-2021
Service Advisor TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SFR198Y	5T13NZC1	28-06-2019	WVGZZZ1TZKW059334	Touran Comfortline EQP 1.4 TSI 110kW DSG	20,750

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5TA813309A	End Plate	1	pcs.	400.18	#1	400.18	428.19
	END PANEL OUTER						
N 91017602	Weld Stud	4	pcs.	0.96	#1	3.84	4.11
D 007500A2	Zinc Spray	1	pcs.	62.88	#1	62.88	67.28
D 180003M2	2k-Body Adhesive	1	pcs.	428.72	#1	428.72	458.73
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	64.15	#1	64.15	68.64
	LABOUR	7	pcs.	840.00	#1	5,880.00	6,291.60
	SPRAY PAINT	6	pcs.	800.00	#1	4,800.00	5,136.00
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	R&R REAR LUGGAGE TRIM	1	pcs.	840.00	#1	840.00	898.80
	REAR NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00
	CHINA TAIPING DIRECT SETTLEMENT						
	DOA : 19/01/2021						
	TP VEH : GBJ5231R						
	SURVEY BY :						

Quotation valid till 26-01-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	22,821.86	7%	1,650.73	23,581.86	25,232.59
Total	760.00	22,821.86		1,650.73	23,581.86	25,232.59

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

VW WAGEN CENTRE SINGAPORE
Sandra Road
Tel: 159934
Fax: No. 189101494Z
No. M200985052



Quotation

Non binding - Preview

Page	3/3
Document no.	
Document date	19-01-2021
Customer no.	5211001170
Customer GST-ID	200208384E
Dealer	30001
Job order number	2021002748/ 1
Job order date	19-01-2021
Service Advisor	TIOU CHUAN CHEE

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
EE
JIAN WEN, JEREMY
114 CLEMENTI STREET 13
#02-63
Singapore 120114

License plate	Model code	First registration	VIN	Model	Mileage
SFR198Y	5T13NZC1	28-06-2019	WVGZZZ1TZKW059334	Touran Comfortline EQP 1.4 TSI 110kW DSG	20,750

Rashid
Hp 9001068

5-6 days

21/01/2021 @1500

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: