

AUBURN AUTO PTE LTD
 UEN : 200805305G
 176 Sin Ming Drive Autocare #04-18, Singapore 575721
 Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Vehicle Number : SMS7223Z

Make & Model : Toyota
 Wish

2007

Quantity	Description	Repairer's Estimate
	BACK	
1	REVERSE SENSOR	\$80 - NDX
1	RIGHT TAIL LIGHT BRACKET	\$120 NDX
1	END PANEL GARNISH	\$230 NDX
1	TAIL LAMP LOWER BRACKET	\$120 NNX
1	REAR RIGHT BUMPER RETAINER	55.60 \$180 NEC ✓
1	REAR RIGHT TAILLIGHT BRACKET	\$120 NDX
1	REAR LEFT TAILLIGHT BRACKET	\$120 NDX
1	REAR RIGHT WHEEL BEARING	\$150 } NDX
1	REAR LEFT WHEEL BEARING	\$150 } NDX
1	SPARE TYRE BOARD	\$80 } NDX
1	BOOTLID WEATHERSTRIP	\$120 } NDX
1	BUMPER BRACKET	✓ \$150 BT ✓
1	REAR RIGHT ABSORBER	\$230 } NDX
1	REAR LEFT ABSORBER	\$230 } NDX
1	REAR RIGHT MUDGUARD	\$80 } NDX
1	REAR LEFT MUDGUARD	\$80 } NDX
1	LEFT BOOTLID LAMP	\$200 } NSX
1	RIGHT BOOTLID LAMP	\$200 } NSX
1	LEFT TAIL LIGHT	✓ \$200 BR ✓
1	RIGHT TAIL LIGHT	\$200 NDX
1	BOOT LOCK	\$120 NDX
1	REAR UNDERCARRIAGE	\$900 NDX
1	BOOT LID	✓ \$650 DD ✓
1	SPARE TYRE WELL	\$120 } NDX
1	BOOT INTERIOR LINING	\$250 } NDX
1	REAR BUMPER	✓ \$450 DD ✓
1	END PANEL	590.00 \$800 DD ✓
		2095.60
	LABOUR & MISC	@ 259.00 1571.70
1	Checking of wiring, lighting and resetting	\$300 50.00 ✓
1	Remove and refit rear undercarriage	\$500 NNX
1	Wheel alignment	\$100 NNX
1	Remove and replace damaged parts	\$800 200.00 ✓
1	Apply undercoating on repaired and replaced panel	\$800 480.00 ✓

1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	600.00 \$1,500 ✓
1	Respray including polishing and waxing on the changed body parts, repaired portortions where consistent to the accident	600.00 \$1,000 ✓
Total Repair Cost :		\$11,330

Survey
20/1/2021

Tarim bin
1400hrs

Resurvey
21/1/2021

Tarim bin
1215 hrs

PARTS 1570.70
LABOUR 1850.00
3421.70
@ 20% 684.34
2737.36

45 2750/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

14000113/22