

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 27 January 2021 1:55 PM
To: Sbk E; SUR
Cc: Naz (LKKAUTO)
Subject: RE: FBN 6789X-DOA: 29/12/20 (AIG OD)
Attachments: FBN 6789X RESURVEY MARKED ESTIMATE.pdf; FBN 6789X SUPPLEMENTARY.pdf

Dear Mr Kwan,

Supplementary approved.

After paint photos for NEW / OLD Parts for items

- 1) *FRONT LEFT FORK ASSY
- 2) STEERING STEM
- 3 HANDLE BAR
- 4) SPORT RIM FRONT
- 5) RIGHT FORK ASSEMBLY
- 6) METER ASSEMBLY

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 26 January 2021 7:38 AM
To: 'Sbk E' <sbk5643e@yahoo.com>; SUR <sur@lkkauto.com>
Cc: Naz (LKKAUTO) <Naz@lkkauto.com>
Subject: RE: FBN 6789X-DOA: 29/12/20 (AIG OD)

Dear Mr Kwan,

Kindly refer to our email below.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sbk E <sbk5643e@yahoo.com>
Sent: Monday, 25 January 2021 8:57 PM

To: SUR <sur@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: Naz (LKKAuto) <Naz@lkkauto.com>

Subject: Re: FBN 6789X-DOA: 29/12/20 (AIG OD)

Dear Veron,

Please confirm that we can proceed with this repair for damaged items including unconfirmed and supplementary. Please confirm that only FRONT LEFT FORK ASSY, HANDLE BAR , SPORT RIM FRONT are required with the after paint photos only? Thank you.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Monday, January 25, 2021, 04:53:27 PM GMT+8, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Mr Kwan,

As instructed by our client, please proceed to repair the **insured vehicle FBN 3789X, (Excess \$300) on Lump Sum Repair.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

After paint photos for all NEW / OLD Parts for items FRONT LEFT FORK ASSY, HANDLE BAR , SPORT RIM FRONT required.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

