# TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGPORE 539186 TEL: 6385 1171 BUS. REG. NO. 53176519M

15th January 2021

Our Ref: CL20083 Your Ref: SHB6235U

India International Insurance Pte Ltd Motor Claims Department

64 Cecil Street #04-05 IOB Building Singapore 049711

Dear Sirs,

### ACCIDENT INVOLVING SKV2830L AND SHB6235U ALONG TAMPINES AVE 5 ON 12.09.2020

We are the representative for Lim Ping Guan, whose vehicle registration number SKV2830L was damaged in the above accident.

We are instructed to claim for damages against your insured in connection with the above-captioned road traffic accident driven by your insured.

We are instructed that the accident was caused by your insured's negligence and/or management of motor vehicle registration SHB6235U. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:-

Cost of repairs	\$4	,700.00
Loss of rental for 04 days @\$128.40	\$	513.60
Survey fee	\$	568.00
LTA search fee	\$	7.45
	\$5	,789.05

Enclosed are the supporting documents for your perusal:-

LTA search Repair bill

Kindly let us have your payment of \$5,789.05 in our workshop's name within the next 14 days.

Please do not hesitate to contact our Ms Tan at 9838 8224 or email motor@iaconsultingsg.com should you have any queries on your matter. We thank you for your kind attention and appreciate your quick remittance.

Yours faithfully,

Encl.



Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

21-7068

Date:

8/12/2020

INVOICE NO.

7068

**Lim Ping Guan** 

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01-556 Singapore 539187

Registration No.

SKV2830L

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

		Total amount	\$568.00
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$568.00
S/No.	Description of Services Provided	Qty	Amount

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

~

L.L. Tan (Ms)

**Principal Consultant** 

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd www.iaconsultingsg.com



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference:

21-7068

Date:

8/12/2020

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01- 556 Singapore 539187

Dear Sirs

RE:

Road Traffic Accident on 12/9/2020

**Lim Ping Guan** 

In accordance with your instructions received in this office or

30/11/2020

, we made arrangements to

examine the vehicle on

30/11/2020

at above-mentioned address. The following data was

recorded:

### Vehicle details


Make	Toyota	Registration	SKV2830L
Model	Harrier	Chassis	ZSU600052118
Colour	White	Gearbox	Auto
Odometer	75619km	Paintwork	Good
Steering	Good	Brakes	Good
Condition	Good		

### Tyre Depths

Front left	235/55R18	85% Michelin
Front right	235/55R18	85% Michelin
Rear left	235/55R18	85% Michelin
Rear right	235/55R18	85% Michelin

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

### Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$4,700.00 and 6 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd www.iaconsultingsg.com



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7068

Date

8/12/2020

Page

2

### Section A: Damaged Parts Assessment

Section A	. Damageu i	aits Assessin	Cit	
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items:				
Rear bumper (orginal)	1	deformed/cut	1024.50	1024.50
Rear end panel	1	repair.respray	758.90	0.00
Rear exhaust pipe	1	rebuild	1425.50	0.00
Rear bumper sponge	1	damaged	112.50	112.50
Rear exhaust pipe headseal @\$185.00	2	grazed	370.00	370.00
W 7.1 1.2 000 2000	Sub- Total	costs	3691.40	1507.00
Percen	tage discount :	25%	922.85	376.75
	s for parts	2768.55	1130.25	
Special Nett Items: Rear bumper clips Rear bumper lower (bodykit) Rear bumper lower lid (bodykit) Rear bumper diffuser (bodykit) Reverse sensor	set  1  1  1  1  Sub-Total cost	necessary damaged holder torn damaged malfunction	55.00 677.40 785.00 845.80 280.00	
Parts Repair				
•	*	•	0.00	0.00
	Sub- Tota	l costs	0.00	0.00
	Total costs f	5411.75	3773.45	

<sup>•</sup> Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd

 <sup>■</sup> IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd www.iaconsultingsg.com



Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7068

Date

8/12/2020

Page

3

### Section B: Labour Cost Calculation

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

	Hour	rly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	48.00	14	\$ 672.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material. (front door, side skirt, bonnet, front bumper / lower lid, front fender)	:	Sub-con	tract work.	\$ 700.00
Apply rust proofing on the adjacent panels.	:	Sub-con	tract work.	\$ 50.00
Remove and rebuild exhaust system	\$	45.00	2	\$ 90.00
Remove and replace rear reverse sensor & conduct distance safety setting	\$	48.00	1.7	\$ 81.60
Specialist charges - Dignostic fault code / reset				\$ 150.00
Wiring and bulb checking	\$	48.00	0.5	\$ 24.00
	£7	Total la	abour cost	\$ 1,767.60

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd www.iaconsultingsg.com



Singapore 41780

No.25 Kaki Bukit Road 4

Hotline: 6385 1171

#06-46 Synergy @KB

Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7068

Date

8/12/2020

### Section C: Summary Table of Total Repair Cost

Desc	cription	Cost	
Damaged Parts Assessment (See section A)		\$3,773.45	
Further discount	20%	\$754.69	
Recommended cost of parts		\$3,018.76	(1)
	t Calculation ection B)	\$1,767.60	(2)
	epair Cost to hundred)	\$4,700.00	(1) + (2)

We would recommend a sum of	\$4,700.00	and	6	working days for repair.
No further items will be approved	without our expr	essed written agre	ement. Any sig	nificant additional
items will be subject to a supplement	entary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council


ACTA certified Trainer, Singapore


Enterprise Singapore - Recognised Certification for Management Consultants


IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)


- Impact Analysis Consulting Pte Ltd
   Impact Analysis Academy Pte Ltd
   IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd www.iaconsultingsg.com



























































































### > Back to OneMotoring



**Land Transport Authority** 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

21 Sep 2020 / 09:59:28

Receipt Date/Time: 21 Sep 2020 / 09:59:28

### Tax Invoice/Receipt

Receipt No.: ITNET-00000-200921-000600

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHB6235U As at 12 Sep 2020/17:05:00 Insurance Co: INDIA INT'L INS PTE LTD Insurance Enquiry - SHB6235U Enquiry Fee		7.00	0.49	7.49
20200921095841219377			-0	
	Sub-Total	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20200921095849209	Direct Debit: eNE (Internet Banking		7,45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

### THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

120 Lower Delta Road #02-15 Cendex Centre Singapore 169208 Tel: 6738 7777 Fax: 6738 6666
ACRA No: 20-0106276-D GST Reg. No: 20-0106276-D
24 HOURS HELPLINE: 6223 1122

TO OIL			
VEHICLE	HIRING	<b>AGREEMEI</b>	٧T

VHA No: A 42346

	•			HIRING	AGREEMEN	41	Wo	orkshop: /	DIFLE	1
4	HIRER'S	PARTICULAR			Hirer's Own Vehic	cle No: SKV 2	830 Repla	ce Veh No		=
ame (as in I/C)	LIM	DING GI	unny 1		Loan Vehicle No:	SLF 388	IK	VR No		
RIC/Passport No		Date of Bir	th: 23 16 1960	1	Make & Model:	1-1 VEZZ	4.1.5.	/	ual Group:	
ddress: 287	Tampi	NES ST 22	Age:	.   -		CHARGES		- Contract		5.42
<b>G</b> G1033.	# 04	-286	s(52028)	-,  -	Daily 4	day @\$	120	Per day	\$440	cts
ame & Address o	f Employer			11-	Weekly/Monthly	week @\$	Per week		1783	V
			V 1	- 11	Others					
ecupation		Driving E	21/0/200	11	CDW/PAI	@\$	Per da	y/Monthly		1
riving Licence No	:	Passed D	Date:	- 1 1-	Delivery/Collectio	n Svc	-			1.
/L Type: Local/Int	VOthers:	1600	CHILLE	-	Deliver y/Concord	Min Estate Marie	GST	7%	<del>+</del> 33	60
		NE CO			A 14 %			B-TOTAL	\$513	60
	DRIVER'	S PARTICULA	RS		OR No:	E 1/4	1/2 3/4	F	13.5	-
Name (as in I/C)					Petrol Level OUT					—
NRIC/Passport N	0:	Date of Bi	irth:		Surcharge IN					
Address:			Age:		Firstkn	FREE per day	GST			
			S(	, ) []	Excess mileage is c	chargeable s per km	TOTAL C	HARGES		
Occupation		Driving I		Yrs	Control of the Assessment	Note the Winder	SEEK WINEK W	REK WERE	W. S. K. W.	FK W
Driving Licence	No:	Passed / E	xpiry Date:		CAN THE RESERVE THE SECOND TO	マグ・スペン・カ・スペース ファイン・ス・ファイン・ス・ファース・スペース・スペース・スペース・スペース・スペース・スペース・スペース・ス	ションヤファションマファ ファファションヤンテンド	スマグイメン	CHANGE WORK	SH-K
D/L Type: Local/	Int'l/Others:		Contact No:		BANKARAN BAR	ママグ・スママン・スマヤ マグ・ス・スマン・アンド・ス	ションマンカ・カンカンティ	スペーク・ディン	THE NEW YEAR	OVSKS
					NON WAIVER EX ACCESSORIES C	CESS (Subject to	GST): \$ QU	CO   Rad	io / CD Cartri	78-26-3
INDICATE:				>	M					
A - Accidents D - Dents	0				Hirer's Signature	:	Ad	ditional Dr	iver's Signat	ure :
S - Scratches X - Crack	B				SINGAPORE Use		-			
			on both sides of this a d traffic infringement information I have		ven BKW Rent A	Car Pte Ltd in	connection v	with this a	greement is	s true.
years and and quality damages  2. All vehicle A service the fail to 3. No refunder any law where appeared lings of 5. Vehicle struithout pripenalty fee of non-disc.  6. The hirer and caused, all whatsoever  7. The hirer hirer and the period of the struithout pripenalty fee of the struithout pripenalty fee.	and the authorized be holding valid of field driving experile costs to be Borne I as are supplied with charge of \$5 on top return the vehicle a d for early return of the return at the rate plicable. Any return or trafficking, smuggictly for Singapore or written consent of \$200 in addition losure of Malaysia and/or driver shall be traffic violations, for reason in respect to dor driver shall be traffic violations, for reason in respect to the property of the	iving licenses and have note. Failure to observe by the Hirer/the Author petrol and should ret or of a petrol surcharge the appropriate petrol vehicle. The hirer shall is shown per hour per of is after our operation is purpose (For instance lying), is strictly prohib use only and may no of BKW Rent A Car P half to the appropriate usage. It responsible for all of the said penallies impoor of or in connection with the responsible for all of the responsible for all of the responsible for all of the said the said penallies imports of the said the responsible for all of the said the said said the said said the said said the said	turned with petrol level in e is payable by the hirer of level. If be liable for additional day, inclusive of CDW ar thours will be charged a e: in connection with the	kewise. should charges addor PAI s a full eff, drug apore le for a e case soever	suffered or incur vehicle. Full exc The owner rese occurred. Any d 8. Smoke or permit offensive smell in the cost of remo 9. The Hirer agree locked keys ins in the event the such occurrence. 10. In case of accide report must be all liability from the event of an 11. The hirer/Drive in the car is sufficient water 2. All customers's ourpose of con	made within 24 hot all parties claim. Fu accident r also have the resi ficient and do not of Any damage to the data will be kept strapleting the sales to the agree to the per the sales to the per sales to the desales to the per sales to	oct of the vehicle to be paid immediate place an replace an replace an replace and replace	or the use of attely in the co- cement vehicle are the hirer and response trans, loss of tank, loss of tank loss	r the operation over the operation and cole if an accided workshop, a not allowed. For this cole is a cole if an accided workshop, and the cole if an accided with the cole if and does not breef driver, y used for the grantlers,	Any I bear I bear Any I bear
Date Out	Time Out	Mileage	Check By		Remarks				0	The same

Yor. Hirer's/Driver Signature Return Of Vehicle: The Hirer Driver Is Required To Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Duestioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc)

Remarks Check By Mileage Time In Datelin 1:12





# **TAX INVOICE**

GST REG. NO.: 200106276D

3. 110 2001062/6D		
DATE	INVOICE NO.	
16-Dec-2020	A 42346	

INVOICE TO.	•	
LIM PING GUAN 282 TAMPINES ST 22 #04-286 SINGAPORE 520282		

	VHA NO.	DUE DATE	VEH NO.
	Λ 42346	16-Dec-2020	SLE 3881 K
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 30 NOVEMBER 2020 TO 04 DECEMBER 2020 YOUR REF: SKV 2830 L	4	120.00	480.00
			3
GST @ 7%			\$33.60
TOTAL			\$513.60

All cheques must be made payable to BKW Rent A Car Pte Ltd. Please write the vehicle and invoice number on the reserve.

### **BKW Rent-A-Car Pte Ltd**

Lower Delta Road #02-15 Cendex Centre (S) 169208 Tel: 6738 7777 Fax: 6738 6666

ACRA No: 200106276D GST Reg. No: 20-0106276-D Website: www.bkw.sg
A subsidiary of BKW Automobile Pte Ltd



## TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186 TEL: 63851171 FAX: 63851141

### INVOICE

: CL20083 Invoice No. To: Lim Ping Guan

22/12/2020 Date SKV2830L Vehicle No.

No.	Description	Qty	Un	it Price	A	mount
1	REPAIR COST		\$	4,700.00	\$	4,700.00
					l.	
-				Total:	\$	4,700.00

Payment by cheque should be crossed and made payable to 'Triple-T Automobile'

Authorised Signature

### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

Contact Number

**EMail Address** 

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	14/09/2020 18:27
Date Of Accident	12/09/2020 17:05
Exact Location Of Accident	ALONG TAMPINES AVE 5
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKV2830L
Insured/Policyholder	
Name Of Registered Owner	LIM PING GUAN
NRIC No	SXXXX449B
Email Address	BRENDALIM100@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-86661616
Alternative Phone No	OFFICE-86661616
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HARRIER 2.0 PREMIUM AT AIRBAG 2WD
Exact Purpose for which vehicle was being used time of accident	at
Are you claiming under your own insurance policy for repair to your vehicle?	y NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA551209
Cover Note Number	05/09/2020-05/09/2021
Driver	
Name of Driver	LIM PING GUAN
NRIC No	SXXXX449B
Date Of Birth	23/10/1969
Occupation	INDOOR
Date Of Driving Pass	31/08/2001
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86661616
Fax Number	

OFFICE-86661616

BRENDALIM100@YAHOO.COM.SG

Address

282 TAMPINES ST 22

04-286

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

1

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

DRIZZLING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

4

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

TRAFFIC POLICE DIVISION HQ

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

ИО

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FOOTAGE WITH OWNER

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SHB6235U

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### **DETAILS OF INJURED PERSON 1**

Name

LIM PING GUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SKV2830L

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

### Sketch Plan Pg. 1

### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the purpose(s).
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

**Driver's Signature** 

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: U NRIC/FIN No.:

### Sketch Plan Pg. 2

		A-sk	1787		
	A	(4 ) C	1.2070	حد .	
	(B)	17 - 3	HB 623	51)	
	7		10020		
ESCRIBE CIRCUMSTANCES C	OF THE ACCIDENT				
- 4 / + 1					
Reser to po	lice report				
Refer to po	lic report				
Refer to po	lic report				
Refur to po	lic report				
Refu to po	lic report				
Refu to po	lic report				
Refer to bo	lic report				
Refer to po	lic report				

DECLARATION

I/We declare the foregoing particulars are true in every respect.

against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from

the day of occurance.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

ntre Personnel's Signature Reporting Name: NRIC/NONO.:

Claim Op / TP at other workshop

Claim OD

Claim TP

### POLICE REPORT Pg. 1





Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 3 Report No. T/20200912/7023

REPORT OF	A TRAFFIC	ACCIDENT			
Date/Time Report Made: 12/09/2020 22:24			Vide Report No.:		Station Diary No.:
Informant	's Particu	ars			
Name of Ir LIM PING			Address: 282 TAMPINES STREET 22 #	04-286 SIN	GAPORE 520282
ID Type / I NRIC NO /		9B	Contact No.: Home/Office: Mobile: 86661616		
Nationality SINGAPOI		N	Email: brendalim100@yahoo.com.sg		
Sex: Male	Age: 50	Date of Birth: 23/10/1969	Type of informant. Driver		
Race: Chinese			Language: English	Institution	/ School Name:
Occupation:			Driving Licence Information: Class: 3	Date of Ex	piry:

Canaral Inform	nation of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 12/09/2020 17:05	i .	Type of Location: Bend
Location: TAMPINES A	VENUE 5				
Weather: Drizzling		Road Surface: Wet		50 Ki	
Traffic Flow: Traffic C		Traffic Control: Not Controlled		Heav	
Type of Collisi	on: ng Vehicles - Head On				ne conveyed by ulance:

Vehicle No.	Туре	Make	Model	Color	Conditio	No of
SHB6235U	Car	HYUNDAI		Blue	Slightly Damaged	0
SKV2830L	Car	TOYOTA	Harrier		Slightly Damaged	0

### POLICE REPORT Pg. 2



Details of Vehicle Insurance

Effective

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

2 of 3 Report No. T/20200912/7023

**Expiry Date** 

### CONTINUATION OF REPORT

Details of V		Insurance No	Effective	Expiry Date
Vehicle No.	Insurance Company			05/09/2021
SKV2830L	AXA INSURANCE SINGAPORE PTE	GA551209	05/09/2020	03/09/2021
511720002	LTD			<u> </u>
Details of Fe	erson invoived			
Any Pedestri	an Involved: No			
	trians Injured: NIL	Use of Pedestrian Cros	ssing: NA	
Driver	_ i _ f . fildu, =v'i _ h		000071405	
Name	LIM PING GUAN	ID No.	S6937449E	3
Deleted Vobi	cle SKV2830L (Car)	Contact No	. 86661616	
Related Vehi	CIE SKV2050E (Cal)			
			21	

Class: 3 Class of MOUNT ALVERNIA HOSPITAL Hospital/Clinic Date of Expiry: NIL Driving Licence & Expiry 12/09/2020 Date 12/09/2020 Serious Degree of 05 No. of Days granted Medical Leave

### Brief Details.

I am moving and approaching the bend, i feel a big impact hiting my rear. The rear taxi(SHB6235U) hit my car. i felt my back sprain and neck discomfort and decided to proceed to the A&E at Mount Avernia. I was given 5 Days MC from the Doctor.

### POLICE REPORT Pg. 3





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20200912/7023

CONTINUATION OF REPORT

Sketch Plan	
Informant is t	at able to provide sketch

**Authentication Stamp** 

NP168

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 12/09/2020 22:24
Officer In Charge Of Case: TP / TPHO / JUREMAH BINTE AHMAD Contact No.: 65476219	Classification Of Case: