




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN : TAN JUN HONG			Ref: CS3/ASM21001005/T1tf3e2 Date: 09/02/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 8761J	Veh. Inspected	SJM 1362L
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S1M030WQ	Excess (\$)	0.00
	Assign From	TAN JUN HONG	Assign Date	21/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053HY9305084710	Colour	SILVER
	Odometer	170444 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	WEST LAKE	6 mm
	L/H Front Tyre	185/60 R15	WEST LAKE	6 mm
	R/H Rear Tyre	185/60 R15	WEST LAKE	6 mm
	L/H Rear Tyre	185/60 R15	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General Information				
	Accident Date	15/01/2021	Inspect Date / Time	21/01/2021 (05:00 PM)
	Survey held at	PAUL HOE ENTERPRISE PTE LTD 1 KAKI BUKIT AVENUE 6, #01-107, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$6,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

Report Ref No. CS3/ASM21001005/T1tf3e2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.