

SJE : _____ Vehicle Nos : **SMT 5100 C**
 Date of Survey : _____ Model : **LEXUS IS300**
 Date of ReSurvey: _____ **After-Paint:** _____ Year : _____
 Contacts : _____ Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: 2018

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	BOOTLID	1	\$ 780.00	\$ 780.00
2	BOOTLID LOGO	1	\$ 190.00	\$ 190.00
3	BOOTLID INNER LOCK	1	\$ 480.00	\$ 480.00
4	BOOTLID INNER LOCK STICKER	1	\$ 45.00	\$ 45.00
5	BOOTLID LAMP LH	1	\$ 850.00	\$ 850.00
6	BOOTLID INNER TRIM BOARD	1	\$ 480.00	\$ 480.00
7	REAR BUMPER	1	\$ 1,296.00	\$ 1,296.00 989.00
8	REAR BUMPER SIDE RETAINER	2	\$ 95.00 145.80	\$ 291.60 190.00
9	REAR BUMPER SIDE BRACKET	2	\$ 85.80	\$ 171.60
10	REAR BUMPER CENTRE BRACKET	1	\$ 118.40	\$ 118.40
11	REAR BUMPER REINFORCEMENT	1	\$ 738.10	\$ 738.10 670.50
12	REAR BUMPER REINFORCEMENT BRACKET	2	\$ 189.50	\$ 379.00
13	REAR BUMPER REFLECTOR LH	1	\$ 89.60	\$ 89.60 ✓
14	REAR BUMPER DIFFUSER	1	\$ 687.00	\$ 687.00 250.00
15	REAR BUMPER REVERSE SENSOR	1	\$ 265.00	\$ 265.00 1,060.00
16	REAR END PANEL	1	\$ 975.10	\$ 975.10 780.00
17	REAR END PANEL TOP GARNISH	1	\$ 598.00	\$ 598.00
18	TAILLAMP LH	1	\$ 980.00	\$ 980.00 897.00
19	TAILLAMP LOWER BRACKET LH	1	\$ 110.00	\$ 110.00
20	EXHAUST PIPE LH	1	\$ 1,523.00	\$ 1,523.00
21	EXHAUST PIPE CHROME TIP LH	1	\$ 414.00	\$ 414.00
Parts Sub Total :				\$ 12,256.40
DISC 10%				\$ 1,225.64
PARTS TOTAL :				\$ 11,030.76

NDX
 BR ✓
 NEC ✓
 NN ✓
 NN ✓
 DD ✓
 NS ✓
 BR ✓
 BR ✓
 DL ✓
 DD ✓
 NDX
 BR ✓
 NN ✓
 NDX
 3866.10
 386.61
 3479.49

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	SUNDRIES	1	\$ 80.00	\$ 80.00
2	BOOTLID SEALANT	1	\$ 100.00	\$ 100.00
3	BOOTLID LAMP SEAL	1	\$ 60.00	\$ 60.00
4	BOOTLID LAMP CLIPS	1	\$ 50.00	\$ 50.00
5	BOOTLID INNER TRIM BOARD CLIPS	1	\$ 50.00	\$ 50.00
6	REAR BUMPER CLIPS	1	\$ 50.00	\$ 50.00 30.00
7	REAR BUMPER DIFFUSER CLIPS	1	\$ 50.00	\$ 50.00 30.00
8	REAR BUMPER REVERSE SENSOR SEAL	1	\$ 60.00	\$ 60.00 240.00
9	REAR END PANEL SEALANT	1	\$ 100.00	\$ 100.00 40.00
10	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ 50.00
11	TAILLAMP SEAL	1	\$ 60.00	\$ 60.00
12	TAILLAMP CLIPS	1	\$ 50.00	\$ 50.00 30.00
SPECIAL NETT TOTAL :				\$ 940.00

NN ✓
 NN ✓
 NEC ✓
 NEC ✓
 NN ✓
 NN ✓
 NEC ✓

Nos.	LABOUR	S\$	
1	R&R BOOTLID COMPONENT	\$	150.00
2	R&R REAR BUMPER REVERSE SENSOR	\$ 60.00	100.00
3	CHECK WIRING	\$ 30.00	100.00
4	DIAGNOSTIC RESET FAULT CODE	\$ 20.00	300.00
5	UPHOLSTERY	\$	200.00
6	PANEL BEATING	\$ 600.00	1,000.00
7	RUST PROOFING	\$	200.00
8	SPRAY PAINTING	\$ 400.00	1,000.00
LABOUR TOTAL :		\$	3,050.00

X
/
/
/
/
NNX
/
NNX
/

Survey 21/1/2021
1300hrs
Tatum M

Resurvey 22/1/2021
1530hrs
Tatum L

LABOUR TOTAL :	\$	3,050.00
		1210.00
PARTS TOTAL :	\$	11,030.76
SPECIAL NETT TOTAL :	\$	940.00
LABOUR TOTAL :	\$	3,050.00
GRAND TOTAL :	\$	15,020.76

Before Paint 22/1/2021
1700hrs
M

PARTS	3479.49
SN	190.00
LABOUR	1210.00

Part by Part repair

Repair days 5

4879.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: