



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 7115U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RHS COWLING	GRAZED / CRACKED	353.00	353.00
1	RH LOWER COWLING	GRAZED / CUT	234.00	234.00
1	RH STEP COVER	GRAZED / CUT	155.00	155.00
1	RH STEP MAT	DEFORMED	95.00	95.00
1	RH PILLION FOOTREST	GRAZED	105.00	105.00
1	HANDLEBAR	BENT	164.00	164.00
1	BAR END WEIGHT RH	DENTED / GRAZED	39.00	39.00
1	FRONT BRAKE LEVER	DENTED / GRAZED	59.00	59.00
1	WING MIRROR RH	CRACKED	96.00	96.00
1	REAR MUDGUARD	DEFORMED / GRAZED	47.00	47.00
1	EXHAUST PIPE	SERVICEABLE	440.00	-
1	EXHAUST GUARD	GRAZED / CUT	87.00	87.00
1	REAR COWLING LH	GRAZED / CRACKED	220.00	220.00
1	REAR COWLING EMBLEM LH 'PCX'	NECESSARY	80.00	80.00
1	REAR COWLING EMBLEM LH '150'	NECESSARY	44.00	44.00
1	SWING ARM	SERVICEABLE	470.00	-
1	REAR RIM	NOT NECESSARY	545.00	-
1	AIR CLEANER COVER	SERVICEABLE	92.00	-
1	DRIVE COVER	GRAZED	553.00	350.00
	LESS 10% DISCOUNT		-387.80	-212.80
			3,490.20	1,915.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	DENTED	20.00	20.00
1	REAR TYRE (SN)	NOT NECESSARY	180.00	-
1	SET REAR SHOCK ABSORBER (SUPRIMO) (SN)	TO REPAIR SEE LABOUR	650.00	-
			850.00	20.00

Report Ref No. CS3/INC19012166/T1qd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR RENEW DAMAGED PARTS, RE-ALIGN AFFECTED AREA. INCLUSIVE OF THE REPAIR OF SET REAR SHOCK ABSORBER (SUPRIMO). TO REPAIR / ALIGNMENT REAR SHOCK ABSORBER.		600.00	300.00
			120.00	120.00
			720.00	420.00
GRAND TOTAL			5,060.20	2,355.20

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00
---	--	--	-----------------

Report Ref No. CS3/INC19012166/T1qd3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.