



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737986

HP: 98888885

Estimation

Date: 19/1/2021

Vehicle: SME5186J

Make / Model: TOYOTA PRIUS

Chassis:

No.	Description	Unit	Unit Price	Amount
1	TAILGATE <i>X R</i>	1	\$ 1,359.00	\$ 1,359.00 <i>X</i>
②	TAILGATE WEATHERSTRIP <i>/CWP</i>	①	\$ 212.00	\$ 212.00 <i>198</i>
3	TAILGATE LOGO <i>X SVC</i>	1	\$ 95.50	\$ 95.50 <i>X</i>
④	TAILGATE EMBLEM PRIUS <i>-NRC</i>	①	\$ 89.40	\$ 89.40 <i>/</i>
5	TAILGATE EMBLEM HYBRID <i>/NRC</i>	①	\$ 82.30	\$ 82.30 <i>/</i>
6	TAILGATE DETECTOR <i>/CRA</i>	①	\$ 321.00	\$ 321.00 <i>120</i>
7	TAILGATE LOCK <i>X SVC</i>	1	\$ 312.00	\$ 312.00 <i>X</i>
8	REAR BUMPER <i>/CRU</i>	①	\$ 658.00	\$ 658.00 <i>/</i>
9	REAR BUMPER SIDE RETAINER <i>/BR</i>	①	\$ 112.00	\$ 112.00 <i>/</i>
10	REAR BUMPER REINFORCEMENT <i>/BT</i>	①	\$ 350.50	\$ 350.50 <i>/</i>
11	REAR BUMPER BRACKET <i>X SVC</i>	2	\$ 114.00	\$ 228.00 <i>X</i>
12	REAR BUMPER LIP <i>/SCR</i>	①	\$ 728.90	\$ 728.90 <i>550</i>
13	REAR BUMPER REFLECTOR <i>X SVC</i>	2	\$ 68.00	\$ 136.00 <i>X</i>
14	REAR FENDER COWLING <i>X SVC</i>	2	\$ 198.20	\$ 396.40 <i>X</i>
15	REAR FENDER INNER TRIM <i>X SVC</i>	2	\$ 589.00	\$ 1,218.00 <i>X</i>
16	TAILLAMP LOWER BRACKET <i>X SVC</i>	2	\$ 82.00	\$ 164.00 <i>X</i>
17	REAR EXHAUST PIPE <i>X SVC</i>	1	\$ 989.00	\$ 989.00 <i>X</i>
18	REAR END PANEL <i>X R</i>	1	\$ 660.20	\$ 660.20 <i>X</i>
19	REAR END PANEL TOP GARNISH <i>X SVC</i>	1	\$ 225.10	\$ 225.10 <i>X</i>
			<i>25%</i>	\$ 8,337.30 <i>2,160.20</i>
			<i>Less 20%</i>	\$ 1,667.46 <i>-25%</i>
			Total	\$ 6,669.84 <i>1,620.15</i>
S/Nett items:				
1	REAR BUMPER CLIPS <i>/NRC</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
2	REAR TAILGATE INNER TRIM BOARD CLIPS <i>X SVC</i>	1	\$ 80.00	\$ 80.00 <i>X</i>
3	REAR NUMBER PLATE <i>X SVC</i>	1	\$ 50.00	\$ 50.00 <i>X</i>
4	REAR NUMBER PLATE GARNISH <i>X SVC</i>	1	\$ 50.00	\$ 50.00 <i>X</i>
5	REAR REVERSE SENSOR <i>X SVC</i>	1	\$ 250.00	\$ 250.00 <i>X</i>
6	REAR END PANEL TOP GARNISH CLIPS <i>X SVC</i>	1	\$ 80.00	\$ 80.00 <i>X</i>
7	REAR END PANEL SEALANT <i>X SVC</i>	1	\$ 60.00	\$ 60.00 <i>X</i>
				\$ 650.00 <i>30</i>
Labour to:				
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00 <i>30</i>
2	TO REMOVE AND RENEW REVERSE SENSOR	1	\$ 150.00	\$ 150.00 <i>30</i>
3	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY	1	\$ 200.00	\$ 200.00 <i>X</i>
4	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00 <i>40</i>
5	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00 <i>40</i>
6	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00 <i>400</i>
7	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00 <i>600</i>
				\$ 2,780.00 <i>1,140</i>

		Parts Replacement Amount	\$ 7,319.84
		Total Amount for Labour	\$ 2,780.00
		Total Amount	\$ 10,099.84

Repair dy - 3 dy,

45

After paint photo

22/01/2021

Sim Pinellu
TP unpropen

1,620.15
30
1,140

2,790.15
- 20.96

2,232.12

415
\$ 2,250
3days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: