

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	22 Jan 2021 13:44	Clim Dtl Modified	Insured Name: -> CHUA CHONG SIN.	[A] LEE SU THING
2	22 Jan 2021 13:44	Clim Veh Model Changed	(202779) MITSUBISHI OUTLANDER 2.0 (A).	[A] LEE SU THING
3	22 Jan 2021 13:44	Clim Created	Reg No: SKL522S. Policy No: 1900166352. Acct Date: 2021/01/21. Claim Type: OD. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)	[A] LEE SU THING
4	22 Jan 2021 13:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
5	22 Jan 2021 13:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/02/02	[A] LEE SU THING
6	22 Jan 2021 13:44	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] LEE SU THING
7	22 Jan 2021 13:44	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	22 Jan 2021 13:44	Adj Adjuster Assigned	[None] -> CHEN TSUE YEE	[A] LEE SU THING
9	22 Jan 2021 15:33	Adj Rpt Initiated		[A] HUEY YON
10	22 Jan 2021 15:33	Clim Dtl Modified	Insured ID: -> 0. Claim Conclusion: -> 3.	[A] HUEY YON
11	22 Jan 2021 15:33	Clim Dtl Modified	JPJ Reg. Date: -> 2019/10/07.	[A] HUEY YON
12	22 Jan 2021 15:33	Clim Details Notified		[A] HUEY YON
13	22 Jan 2021 15:54	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/02/02	[A] SHIAU CHAN
14	22 Jan 2021 15:56	Adj Mandate Request	Cur.Req:4370.75:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
15	25 Jan 2021 12:40	Clim Registration Modified	Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Mithoo Singh, Aashweenjeet Kaur
16	25 Jan 2021 16:03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/02/02. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair	[I] Lim, Kok-Chong
17	25 Jan 2021 16:03	Adj Mandate Set	Approved:4284.51:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From    Date To    Audit Type None  Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2663597	22 Jan 2021 15:33:06	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKL522S		11.00

