

KARZ WORKS PTE LTD

53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK

SINGAPORE 408934

(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

REPAIR PERFORMA INVOICE

FIRST CAPITAL

Vehicle number	JTY6553
Make / Model	YAMAHA Y15ZR
Chassis number	PMYUG0520L0114681
Accident date	12/12/20
Reference	KK2101-31

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1 SET	FRONT FORK	600.00 <i>bl</i>
1	FRONT FENDER	250.00 <i>cut</i>
1	FRONT SIGNAL LAMP LH	120.00 <i>x</i>
1	FRONT FOG LAMP LH	150.00 <i>x</i>
1	FRONT HEADLAMP	350.00 <i>cut</i>
1	FRONT HEADLAMP FAIRING (CENTRE)	380.00 <i>cut</i>
1	FRONT HEADLAMP FAIRING (LH)	180.00 <i>cut</i> <i>X</i>
1	FRONT FAIRING INNER	450.00 <i>cut</i>
1	FRONT FAIRING OUTER	380.00 <i>cut</i>
1	FRONT LH FAIRING	550.00 <i>cut</i>
1	FRONT LH FAIRING LOWER	420.00 <i>X</i>
1	REAR LH FAIRING	500.00 <i>cut</i>
1	PILLION HANDREST	280.00 <i>cut</i>
1	REAR SIGNAL LH	120.00 <i>cut</i>
1	CLUTCH LEVER	90.00 <i>cut</i> <i>X</i>
<i>brake</i> 1	GEAR LEVER	90.00 <i>br</i>
1	GEAR PEDAL	90.00 <i>br</i>
1	STAND	85.00 <i>Ry</i>
1	FOOTREST	95.00 <i>br</i>
1 SET	WING MIRROR	150.00 <i>cut</i>
1 SET	BALANCER	120.00 <i>ms</i>
1	HANDLE BAR	550.00 <i>?</i>
		6000.00
Less 10%		600.00
Subtotal		5400.00
Balance C/F		5400.00

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	STICKER	150. 300.00 <i>at</i>
1	IU UNIT	156.00 <i>cut</i>
1	IU UNIT BRACKET	110.00 <i>bt</i>
1	FRONT NUMBER PLATE	50.00 <i>cut</i> 10
1 SET	GEAR SHIT SHAFT OIL SEAL	24.00 X
2	FORK OIL SEAL	120.00 <i>Net-60</i>
1 BOT	FORK OIL	60.00 <i>Net</i>
Subtotal		820.00
Balance C/F		6220.00
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	TO CHECK WIRING SYSTEM	60.00 <i>30</i>
2	TO REALIGN BODY FRAME	350.00 <i>200</i>
3	TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING	400.00 <i>200</i>
4	TO SPRAY FENDER, SIDE FAIRINGS AND AFFECTED AREAS	500.00 <i>200</i>
Subtotal		1310.00
Grand total		7530.00

Tauphu 97495749
 WP 05 days
 4/8 Resurvey after repair
 *To check part price
 22/1/21 @ 5pm
 *To check MV, repair unit

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: