



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI21001129/Dqd3e2	
			Date: 22/03/2021	
			Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGR 3393T	Veh. Inspected	SJQ 6825P	
Policy No.		Coverage (\$)	0.00	
Claim No.	M12D14802102	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	25/01/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	BMW 520	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBAXG12090DX48264	Colour	BLUE	
Odometer	153778 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	PIRELLI	5 mm	
L/H Front Tyre	225/55 R17	PIRELLI	5 mm	
R/H Rear Tyre	225/55 R17	PIRELLI	5 mm	
L/H Rear Tyre	225/55 R17	PIRELLI	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/01/2021	Inspection Date	25/01/2021	
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	