

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAI	NCE BHD		Ref:	CS/LPC21001140/T1qd3e2	
	300 BEACH ROAD #17-04/07 THE CO	) NCOURSESINGAPORE 199555		Date:	02/07/2021	
				Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGS 6479E	Veh. Inspected		SLF 51D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/21/21/VP05/024162	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		25/01/2021	
2. Vehicle Particulars & Condition						
	Make & Model	PORSCHE MACAN GTS	c.c		2997	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	WP1ZZZ95ZHLB62506	Colour		RED	
	Odometer	106191 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	265/40 R21	PIRELLI		6 mm	
	L/H Front Tyre	265/40 R21	PIRELLI		6 mm	
	R/H Rear Tyre	295/35 R21	PIRELLI		6 mm	
	L/H Rear Tyre	295/35 R21	PIRELLI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	16/01/2021	Inspection Date	е	27/01/2021	
	Survey held at	CHIN CHUAN GARAGE				
		BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				