

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: M607023 Date: 12<sup>th</sup> April 2021

Our Ref: CS1/MSG21001142/Dqe2

## M/s MSIG Insurance (Singapore) Pte Ltd

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

Dear Sir / Madam.

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBA 7106D INSURED VEHICLE: SMF 1834T

ACCIDENT DATE: 25/09/2019

We thank you for your instruction on 07/09/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBA 7106D from M/s STA Inspection Pte Ltd.
- b) Singapore Accident Statement of Vehicles GBA 7106D and SMF 1834T.
- c) Police Report of Vehicles GBA 7106D.
- d) Colour damaged vehicle photographs of GBA 7106D.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GBA 7106D

Make & Model : Toyota Hiace Manual

Year of Registration : 2007

Chassis Number : JTFHT02P400006542

Engine Capacity : 2982 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.