

Udececilia

Not Authorized
L/S \$3300
5 days

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SPORE 417883

VEHICLE No: GBE 7844K

nett item

1PC	TAILGATE	R	\$2,668.00	X
1PC	TAILGATE ,NISSAN, EMBLEM	sticker nee	\$175.00	—
1PC	TAILGATE LOWER MEMBER	Beaf \$22.10	\$688.00	—
2PCS	TAILGATE LOCK LATCHES @215.00	11	\$430.00	X
2PCS	TAILGATE HINGES \$50.00	11	\$100.00	X
2PCS	TAILGATE 'L' LOWER PANELS @145.00	11	\$290.00	X
2PCS	TAILGATE 'L' LOWER PANEL STOPPERS @121.00	11	\$242.00	X
2PCS	TAILLAMPS @208.00	one	\$416	—
2PCS	TAILLAMP BRACKETS @165.00	NS	\$330.00	X
2PCS	DROP SIDEGATES @2998.00	11	\$5,996.00	X
2PCS	DROP SIDEGATE LOWER PANELS @981.00	11	\$1,962.00	X
1PC	REAR SPARE TYRE CHAIN & BRACKET	Beaf 322.50	\$4,551.00	—
1PC	CHASSIS FRAME O/S	R	\$3,800.00	X
			\$21,648.40	

S.NETT				S/N
1SET	70KM/H & 13PAX STICKER	nee	\$25.00	20
1SET	REAR REVERSE SENSOR	one	\$280.00	200
1SET	REAR STEP PANEL BRACKET	Beaf	\$850.00	600
1PC	REAR LICENCE PLATE	Beaf	\$30.00	14
	TO CHECK WIRING		\$50.00	20
	TO DISMANTLE & REPLACING REVERSE SENSOR		\$80.00	50
	TO LIFT UP REAR CARGO DECK FOR REPAIR CHASSIS		\$880.00	300
	TO SPRAY RUST PROOFING		\$180.00	50
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$1,800.00	1000
	TO PUTTY & SPRAY PAINTING		\$1,800.00	600
	TOTAL		\$27,623.40	

LKK Auto Components hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

P-1435-60
102
P-1292-04
S/N-834
L-2020
4146.04
202
3310