



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mohd Ikbar S/o Mohd Ibrahim	Cust No/Name /Mohd Ikbar S/O Mohd Ibrahim
Blk 389 Bukit Batok West Avenue	Reg No/Reg Date SLX5323S / 29/03/201
#10-394	Date In/Mileage / 0
Singapore 650389	Chassis No MMBSTA13AJH002035
Contact No Mobile: 93627163	Engine No 3A92UGT7931
	Make/Model MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	23/01/2021/ 13:05		442 / CocoLu	62223			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3200.00
RENEW REAR BUMPER, BOOTLID, REAR END PANEL								60.00
E PNT88000								2200.00
REMOVE & INSTALL PARKING SENSOR								220.00
E PNT98000								80.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL								40.00
M SUNDRY								30.00
SUPPLY PARKING SENSOR								280.00
M SUNDRY								20.00
APPLY SEALANT FOR ACCIDNET PORTION								748.00
M SUNDRY								28.00
C&C LOGO								28.00
A 54900099								425.00
CHECK WIRING & ELECTRICAL SYSTEM								218.00
A 10028901								157.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								791.00
USING HI-SCAN PRO TEST								69.00
M SUNDRY								21.00
Sundry								66.00
M FACE,RR BUMPER					1.00	748.00	00.00	91.00
M BRACKET,RR BUMPER,RH					1.00	28.00	00.00	96.00
M BRACKET,RR BUMPER,LH					1.00	28.00	00.00	40.00
M PANEL,RR END					1.00	425.00	00.00	
M LATCH,TRUNK LID					1.00	218.00	00.00	
M WEATHERSTRIP,TRUNK LID					1.00	157.00	00.00	
M PANEL,TRUNK LID					1.00	791.00	00.00	
M MARK,THREE-DIA					1.00	69.00	00.00	
M MARK,ATTRAGE					1.00	21.00	00.00	
M TRIM,RR END					1.00	66.00	00.00	
M BUZZER,KEYLESS OPERATIO,RR					1.00	91.00	00.00	
M ANT,KEYLESS OPERATION,RR					1.00	96.00	00.00	
M COVER,RR VENTILATOR					1.00	40.00	00.00	

Confirm & accepted by

Nett 8,908.00
7% GST on 8908.00 623.56
Total Payable 9,531.56

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.