



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN : MARCUS XIAO

Ref: CS/INC21001207/R1vf3e2

Date: 05/03/2021

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 7643M	Veh. Inspected	SJS 5208S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1118562-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	26/01/2021

### 2. Vehicle Particulars & Condition

Make & Model	HONDA FREED 1.5G A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GB31036835	Colour	GREY
Odometer	127339 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	BRIDGESTONE	5 mm
L/H Front Tyre	185/70 R14	BRIDGESTONE	5 mm
R/H Rear Tyre	185/70 R14	BRIDGESTONE	5 mm
L/H Rear Tyre	185/70 R14	BRIDGESTONE	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	14/01/2021	Inspect Date / Time	26/01/2021 ( 11:43 AM )
Survey held at	DAS AUTO & AIRCON SERVICES BLK 9 PIONEER ROAD NORTH #01-58 SINGAPORE 628461		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days