

## NATIONAL ASSESSMENT CENTRE SERVICES (LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park, Singapore 408933, TEL: 68410055 FAX: 68416315

Your Ref : MT/1118386-006 Date: 21st Jan 2022

Our Ref : NS/INC21001214/Qvf3e2

## M/s Ntuc Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 Ntuc Trade Union House Singapore 189556 (The Motor Claims Department)

Dear Sirs/Madam,

## AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHB 630B INSURED VEHICLE: SBC 50R ACCIDENT ON 22/01/2021

Instruction was received to inspect the vehicle Reg. No. SHB 630B. The inspection was conducted on 25/01/2021 at the premises of M/s SMRT Automotive Services Pte Ltd, 60 Woodlands Industrial Park E4, Singapore 757705

The following vehicle information was recorded:

Registration Number : SHB 630B

Make/Model : Toyota Prius Taxi (SMRT)

Year of Registration : 2014 Body Colour : Maroon

Chassis Number : JTDKN36U305747973

Engine Capacity : 1798 cc Speedometer Reading : 694042 km

The vehicle sustained damages at the front and rear portion. The Estimated repair cost of such vehicle is S\$13,900.00 (Sin Dollars: Thirteen Thousand Nice Hundred only.) (Details see photographs enclosed)



## NATIONAL ASSESSMENT CENTRE SERVICES (LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park, Singapore 408933, TEL: 68410055 FAX: 68416315

In view of this repair work, we are of the opinion that it would be uneconomical to proceed with the repairs and recommend it's to be written off as "Total Loss".

(a) If the vehicle to be "Total Loss"

Book Value 26,655.80 (est)

Less: LTA Reimbursement Value (RV) (S\$ 15,412.00)

11,243.80 **Nett Liability** S\$

> S\$ 11,243.80

(b) If the vehicle to be "Repair"

Repair Cost (Est) S\$ 13,900.00

Nett Liability S\$ 13,900.00

(a) - (b) =**(S**\$ 2,656.20)

The amount of estimated saving of S\$2,656.20 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust), MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA, MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA), AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.