

Reply all Delete Junk Block ...

PRI(LKK) \ CMTD2003094/THE - PRE-REPAIR SURVEY TRAFFIC ACCIDENT INVOLVING GBJ4798D AND PC6394T ON 22ND OCTOBER 2020 AT ABOUT 1555 HRS [2101-7022 (SG1) (PD)]

TG

Teo, Grace <grace.teo@sompo.com.sg>

Tue 26/1/2021 1:07 PM

To: Kitty Tan <kitty_tan@rssolomon.com>; Choo, Thelma <thelma.choo@sompo.com.sg>; Admin-D
Cc: Natalie Ng <natalie_ng@rssolomon.com>; Lua Siew Hui <lua_siewhui@rssolomon.com>; Wendy



Without Prejudice

Our Reference : CMTD2003094/THE
Your Reference: RSS/ 2101-7022 (SG1)(PD)]

Hi Kitty,

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

-
-

The survey is conducted on a without Prejudice basis and without any admission of liability.

Aside to **LKK AUTO**,

Please arrange **Mr. Kenneth or Mr. Marcus** to survey **GBJ4798D** on a without prejudice and any admission of liability basis.

Please revert your report upon completion of survey to my colleague, **Ms. Thelma**.

Thank you.

-

Please be informed that our office will relocate to #03-03 at Singapore Land Tower with effect from 1 Dec 2020. Kindly direct invoices and business correspondence to our new registered address.