

Lulu Cecilia

1/5 \$5000

FIA MOTOR TRADING PTE LTD (201202259N)

1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

AIG

: Lim WeiHong

Accident Date : 16-Jan-21

icle No: FBN5682B

Vehicle Model : Kymco Xciting 400S

Estimated Repair Costs

27/1/21

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Windshield <i>scr</i>	\$ 245.00 ✓
1	Windshield inner cowling <i>one</i>	\$ 280.00 ✓
2	Front cowling - L/R/H <i>n/s and</i>	\$ 480.00 <i>1pc</i>
1	Meter outer cowling <i>one</i>	\$ 360.00 ✓
1	Headlamp assy <i>one n/s</i>	\$ 1,050.00 ✓
2	Front inner cowling - L/R/H <i>one</i>	\$ 440.00 <i>1pc</i>
1	Front fender one SVC	\$ 180.00 X
1	Front fork assy <i>scr</i>	\$ 2,040.00 X
1	Front rim <i>11</i>	\$ 380.00 X
1	Front rim shaft <i>11</i>	\$ 68.00 X
1	Front rim bearing <i>11</i>	\$ 45.00 X
2	Front brake disc - L/R/H <i>11</i>	\$ 680.00 X
2	Lower side cowling blue - L/R/H <i>n/s one</i>	\$ 430.00 <i>1pc</i>
2	Lower side cowling matt black - L/R/H <i>n/s one</i>	\$ 430.00 <i>1pc</i>
1	Footstep panel - L/H <i>one</i>	\$ 185.00 ✓
1	Brake lever <i>LH</i> <i>scr</i>	\$ 180.00 ✓
2	Side mirror (1 set) <i>one</i>	\$ 480.00 ✓
1	Handle-bar <i>scr</i>	\$ 210.00 X
2	Handle-bar balancer <i>11</i>	\$ 48.00 X
2	Hand grip <i>11</i>	\$ 58.00 X
1	Side stand <i>one</i>	\$ 48.00 ✓
1	Main stand <i>one</i>	\$ 158.00 ✓
2	Rear side cover - L/R/H <i>one</i>	\$ 520.00 ✓
2	Rear footrest <i>scr</i>	\$ 220.00 X
1	Air filter one <i>11</i>	\$ 360.00 X
1	Air filter box cover <i>one</i>	\$ 180.00 ✓
1	Drove belt cover <i>one</i>	\$ 470.00 ✓
2	Rear handle - L/R/H <i>n/s one</i>	\$ 530.00 <i>1pc</i>
1	Exhaust assy <i>one</i>	\$ 1,780.00 X
1	Exhaust protector - front <i>Dis</i>	\$ 63.00 ✓
1	Exhaust cover centre <i>Dis</i>	\$ 86.00 ✓
1	Exhaust end cap cover <i>one</i>	\$ 58.00 ✓
1	Compartment box <i>for</i> <i>one</i>	\$ 580.00 ✓
1	Lower belly panel - R/H <i>one</i>	\$ 370.00 ✓
		\$ 13,692.00
Less 10%		\$ 1,369.20
		\$ 12,322.80

2806

EROFIA MOTOR TRADING PTE LTD (201202259N)

1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

: Lim WeiHong

Accident Date : 16-Jan-21

Vehicle No : FBN5682B

Vehicle Model : Kymco Xciting 400S

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>Al sen</i>	\$	28.00 <i>10</i>
2	Fork oil <i>11</i>	\$	30.00
2	Fork oil seat <i>11</i>	\$	75.00 <i>7</i>
1	Steering cone (1 set) <i>11</i>	\$	185.00 <i>x</i>
1	Rear box <i>cut</i>	\$	420.00 <i>380</i>
1	Rear box bracket <i>sel</i>	\$	150.00 <i>x</i>
		\$	<u>888.00</u>

S/No. Labour

1	To provide towing service (LOD)	\$	50.00 <i>✓</i>
2	To check wiring and reset headlamp focusing	\$	<i>11</i> 80.00 <i>x</i>
3	To spray paint	\$	480.00 <i>350</i>
4	To provide labour	\$	520.00 <i>300</i>
		\$	<u>1,130.00</u>

Grand Total

\$ 14,340.80

Singapore Dollars: Fourteen Thousand Three Hundred Forty and Cents: Eighty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: