

ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE
SINGAPORE 417868
TEL: 90079247

TO	: CHINA TAIPING	DATE	: 25/1/2021
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT			
VEHICLE DETAILS			
VEHICLE NO	: SGF6650U	<i>Justin</i>	
VEHICLE MODEL	: MITSUBISHI COLT PLUS		
CHASSIS NO	: JMYLTZ23W6Z000428		
ACCIDENT DETAILS	DATE		
	TIME		
THIRD PARTY REQUESTOR / CONTACT		XAVIER / 90079247	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>RH auto</i>	2	\$ 45.00	\$ 90.00
2	REAR BUMPER <i>Del</i>	1	\$ 592.00	\$ 592.00
3	REAR BUMPER SIDE HOLDER <i>re</i>	2	\$ 25.00	\$ 50.00
4	REAR BUMPER REFLECTOR <i>Her</i>	2	\$ 27.00	\$ 54.00
5	REAR BUMPER REFLECTOR <i>Her</i>	1	\$ 342.00	\$ 342.00
6	REAR END PANEL <i>Del</i>	1	\$ 166.00	\$ 166.00
7	REAR END PANEL TOP GARNISH <i>Del</i>	1	\$ 166.00	\$ 166.00
8	TAILGATE <i>Auto</i>	2	\$ 485.00	\$ 970.00
9	TAILGATE LOCK <i>Del</i>	1	\$ 835.00	\$ 835.00
10	TAILGATE WEATHERSTRIPE <i>Auto</i>	1	\$ 374.00	\$ 374.00
11	TAILGATE OUTER MOULDING <i>Del</i>	1	\$ 162.00	\$ 162.00
12	TAILGATE INNER TRIM BOARD <i>Auto</i>	1	\$ 131.00	\$ 131.00
13	TAILGATE REFLECTOR <i>Auto</i>	1	\$ 274.00	\$ 274.00
14	TAILGATE WIPER MOTOR <i>Auto</i>	2	\$ 268.00	\$ 536.00
15	TAILGATE GLASS MOULDING <i>Auto</i>	1	\$ 374.00	\$ 374.00
16	MITSUBISHI LOGO <i>Auto</i>	1	\$ 68.00	\$ 68.00
17	COLT PLUS WORDING <i>Auto</i>	1	\$ 38.00	\$ 38.00
18	REAR FENDER INNER TRIM BOARD <i>Auto</i>	1	\$ 38.00	\$ 38.00
19	SPARE TYRE PANEL TOP COVER <i>Auto</i>	1	\$ 69.00	\$ 69.00
20	REAR EXHAUST PIPE <i>Auto</i>	2	\$ 179.00	\$ 358.00
21	REAR EXHAUST PIPE MOUNTING <i>Auto</i>	1	\$ 494.00	\$ 494.00
		1	\$ 364.00	\$ 364.00
		1	\$ 38.00	\$ 38.00

TOTAL PRICE: \$ 6,379.00
LESS 10% \$ 637.90
SUB TOTAL PRICE: \$ 5,741.10

5520
4968

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 30.00	\$ 30.00 ✓
2	REAR NUMBER PLATE HOLDER <i>old</i>	1	\$ 30.00	\$ 30.00 ✓
3	REAR BUMPER CLIPS <i>on</i>	1 SET	\$ 50.00	\$ 50.00 ✓ 30
4	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00 ✓
5	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00 ✓
6	REVERSE SENSOR <i>new</i>	1 SET	\$ 280.00	\$ 280.00 ✓ 280
7	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00 ✓ 380
8	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00 ✓ 30
9	TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00 ✓
10	REAR FENDER INNER TRIM BOARD CLIPS <i>new</i>	2 SETS	\$ 30.00	\$ 60.00 ✓

TOTAL : \$ 1,120.00

840

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	1800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	920	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	60	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE REAR CAMERA	\$ 100.00	50	
7	TO REMOVE UPHOLSTERY	\$ 150.00	60	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	80	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	120	
10	TO REMOVE EXHAUST PIPE	\$ 150.00	X.	

TOTAL: \$ 3,430.00

2350

ESTIMATE REPORT

TOTAL PARTS COST: \$ 6,861.10

TOTAL LABOUR COST: \$ 3,430.00

TOTAL REPAIR COST: \$ 10,291.10

total: 8/58

L/S: 6.5K

86 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6.5K