



TRANS EUROKARS PTE LTD



FINALIZATION COST OF REPAIRS

| CHINA TAIPING INSURANCE P/L |                              | NAME :          |           | WIP :            |                   | 46428       |             |
|-----------------------------|------------------------------|-----------------|-----------|------------------|-------------------|-------------|-------------|
| 3 ANSON ROAD                |                              | ADDRESS :       |           | EXCESS :         |                   | NIL         |             |
| #16-00 SPRINGLEAF TOWER     |                              |                 |           | DATE:            |                   | 25-Jan-21   |             |
| SINGAPORE 079909            |                              |                 |           |                  |                   |             |             |
| ATTN. : MOTOR CLAIMS        |                              | TEL :           |           |                  |                   |             |             |
| FAX :                       |                              |                 |           |                  |                   |             |             |
| VEH NO :                    | SGX3066G                     | DATE IN :       |           | CONTACT PERSON : | Ronald 63957875   |             |             |
| CHASSIS NO :                | JM6CC1071H0110904            | MILEAGE :       |           | TYPE OF CLAIM :  | THIRD PARTY CLAIM |             |             |
| MODEL :                     | BIANTE                       | DATE REG.:      | 25-May-17 | POLICY NO. :     |                   |             |             |
| <b>NATURE OF WORKS</b>      |                              |                 |           |                  |                   |             |             |
| <b>Parts Description</b>    |                              |                 |           |                  |                   |             |             |
| NO                          | DESCRIPTION                  | PARTS NO        | QTY       | 1st              | Supp              | REVISED     | PRICES      |
| 1                           | FRONT BUMPER                 | MC275-50-221FBB | 1         |                  |                   | \$ 1,170.50 | \$ 1,170.50 |
| 2                           | RETANIER LHS                 | MC273-50-2J1C   | 1         |                  |                   | \$ -        | \$ 48.80    |
| 3                           | RETANIER RHS                 | MC273-50-2H1C   | 1         |                  |                   | \$ -        | \$ 48.80    |
| 4                           | GROMMET, FRONT BUMPER        | MB01W-51-142B   | 2         |                  |                   | \$ 6.40     | \$ 6.40     |
| 5                           | RIVET, FRONT BUMPER          | MA001-50-7C1    | 2         |                  |                   | \$ 7.60     | \$ 7.60     |
| 6                           | FASTENER, FRONT BUMPER       | MGD7A-50-EA1    | 2         |                  |                   | \$ 6.40     | \$ 6.40     |
| 7                           | PIN LOCATOR, FRONT BUMPER    | MGJ6B-50-1K5    | 1         |                  |                   | \$ 4.20     | \$ 4.20     |
| 8                           | GROMMET, FRONT BUMPER        | MBP4K-50-ES1    | 2         |                  |                   | \$ 9.40     | \$ 9.40     |
| 9                           | CAP, FRONT BUMPER            | MC275-50-5A1BBB | 1         |                  |                   | \$ -        | \$ 3.50     |
| 10                          | TAPE PROTECTOR, FRONT BUMPER | MG043-62-864A   | 2         |                  |                   | \$ 7.00     | \$ 7.00     |
| 11                          | REFLECTOR LHS, FRONT BUMPER  | MC273-51-5M0A   | 1         |                  |                   | \$ -        | \$ 124.50   |
| 12                          | REFLECTOR LHS, FRONT BUMPER  | MC273-51-5L0A   | 1         |                  |                   | \$ -        | \$ 124.50   |
| 13                          | STRIPE LHS, FRONT BUMPER     | MC467-50-888    | 1         |                  |                   | \$ 86.00    | \$ 86.00    |
| 14                          | STRIPE LHS, FRONT BUMPER     | MC467-50-878    | 1         |                  |                   | \$ 86.00    | \$ 86.00    |
| 15                          | STRIPE CNETER, FRONT BUMPER  | MC467-50-879    | 1         |                  |                   | \$ 130.10   | \$ 130.10   |
| 16                          | TAILGATE                     | MC2Y3-62-02XF   | 1         |                  |                   | \$ 1,699.70 | \$ 1,699.70 |
| 17                          | WEATHERSTRIP, TAILGATE       | MC273-62-761B   | 1         |                  |                   | \$ -        | \$ 218.30   |
| 18                          | VALVE ONEWAY, TAILGATE       | MGHP9-58-867    | 2         |                  |                   | \$ 24.00    | \$ 24.00    |
| 19                          | FASTENER, TAILGATE           | MB467-68-AC3 34 | 3         |                  |                   | \$ 16.80    | \$ 16.80    |
| 20                          | LOCK, TAILGATE               | MC273-62-310    | 1         |                  |                   | \$ 264.60   | \$ 264.60   |
| 21                          | PIN STUD, REAR WINDSCREEN    | MG21E-63-938B   | 1         |                  |                   | \$ 11.10    | \$ 11.10    |
| 22                          | SPACER, REAR WINDSCREEN      | MC001-50-897    | 2         |                  |                   | \$ 9.40     | \$ 9.40     |
| 23                          | SPACER, REAR WINDSCREEN      | MGJ6A-50-897    | 5         |                  |                   | \$ 64.00    | \$ 64.00    |
| 24                          | FASTENER, REAR WINDSCREEN    | MC273-50-896    | 2         |                  |                   | \$ 16.40    | \$ 16.40    |
| 25                          | FASTENER, REAR WINDSCREEN    | MD204-50-896A   | 2         |                  |                   | \$ 5.60     | \$ 5.60     |
| 26                          | FASTENER, REAR WINDSCREEN    | MEG21-51-146    | 3         |                  |                   | \$ 18.60    | \$ 18.60    |
| 27                          | FINISHER, TAILGATE           | MC273-50-850L   | 1         |                  |                   | \$ -        | \$ 2,018.60 |
| 28                          | CHROME, TAILGATE             | MC330-50-810F   | 1         |                  |                   | \$ -        | \$ 555.30   |
| 29                          | GARNISH LHS, FINISHER        | MC273-50-8F1    | 1         |                  |                   | \$ -        | \$ 18.20    |
| 30                          | GARNISH RHS, FINISHER        | MC273-50-8E1    | 1         |                  |                   | \$ -        | \$ 18.20    |

|                  |                    |                 |   |  |  |           |             |
|------------------|--------------------|-----------------|---|--|--|-----------|-------------|
| 31               | ORNAMENT, SKYACTIV | MC603-51-771A   | 1 |  |  | \$ 117.10 | \$ 117.10   |
| 32               | TRIM, END PANEL    | MC273-68-89XA56 | 1 |  |  | \$ -      | \$ 122.30   |
| TOTAL PARTS      |                    |                 |   |  |  |           | \$ 3,760.90 |
| TOTAL PARTS COST |                    |                 |   |  |  |           | \$ 3,760.90 |

#### SUPPLEMENTARY

| NO               | DESCRIPTION              | PARTS NO      | QTY | 1st | Supp | REVISED   | PRICES    |
|------------------|--------------------------|---------------|-----|-----|------|-----------|-----------|
| 1                | REAR END PANEL <i>bt</i> | MC273-70-750R | 1   |     |      | \$ 303.20 | \$ 303.20 |
| 2                | ANTENNA <i>cra</i>       | MC277-67-6NO  | 1   |     |      | \$ 265.80 | \$ 265.80 |
| 3                |                          |               |     |     |      |           |           |
| TOTAL PARTS      |                          |               |     |     |      |           | \$ 569.00 |
| TOTAL PARTS COST |                          |               |     |     |      |           | \$ 569.00 |

#### Labour Description

| 1  | MZ-BR-REAR04 | TO REPLACE REAR BUMPER AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. |  |  |  | \$ 1,320.00 | \$ 3,780.00 |
|----|--------------|--------------------------------------------------------------------------------|--|--|--|-------------|-------------|
| 2  | MZ-SP-SREAR4 | TO RESPRAY REAR BUMPER AND TAILGATE.                                           |  |  |  | \$ 1,260.00 | \$ 4,800.00 |
| 3  | MZ-BR-GLASS1 | TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.            |  |  |  | \$ 560.00   | \$ 560.00   |
| 4  | MZ-BR-GLASS2 | TO SUPPLY SEALER ON THE WINDSCREEN GLASS.                                      |  |  |  | \$ 120.00   | \$ 120.00   |
| 5  | MZ-BR-REVSER | TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR)                              |  |  |  | \$ 330.00   | \$ 660.00   |
| 6  | MZ-BR-CAMERA | TO TRANSFER REVERSE CAMERA.(WITH REVERSE CAMERA)                               |  |  |  | \$ -        | \$ 660.00   |
| 7  | MZ-BR-PLATE1 | TO SUPPLY NUMBER PLATE.                                                        |  |  |  | \$ -        | \$ 70.00    |
| 8  | MZ-BR-TAILME | TO TRANSFER TAILGATE MECHANISM.                                                |  |  |  | \$ 330.00   | \$ 330.00   |
| 9  | MZ-BR-PLATE1 | TO SUPPLY NUMBER PLATE.                                                        |  |  |  | \$ -        | \$ 70.00    |
| 10 | MZ-BR-ELECTR | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                             |  |  |  | \$ 150.00   | \$ 250.00   |
| 11 | MZ-BR-CAVITY | TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU)      |  |  |  | \$ -        | \$ 250.00   |
| 12 | MZ-BR-REPROG | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.                                |  |  |  | \$ 180.00   | \$ 350.00   |

|                   |              |                      |                    |              |              |
|-------------------|--------------|----------------------|--------------------|--------------|--------------|
| 13                | MZ-BR-SUNDRI | SUNDRIES.            |                    | \$ 20.00     | \$ 100.00    |
| ADDITIONAL LABOUR |              |                      |                    |              |              |
| 1                 |              | TO REPLACE END PANEL |                    | \$ 1,320.00  | \$ 1,320.00  |
| 2                 |              | TO RESPRAY END PANEL |                    | \$ 630.00    | \$ 630.00    |
|                   |              |                      | TOTAL LABOUR       | \$ 6,220.00  | \$ 12,000.00 |
|                   |              |                      | TOTAL PARTS        | \$ 4,329.90  | \$ 7,061.90  |
|                   |              |                      | TOTAL              | \$ 10,549.90 | \$ 19,061.90 |
|                   |              |                      | LESS EXCESS        | \$ -         | \$ -         |
|                   |              |                      | TOTAL AFTER EXCESS | \$ 10,549.90 |              |
|                   |              |                      | GST 7%             | \$ 738.49    | \$ -         |
|                   |              |                      | GRAND TOTAL        | \$ 11,288.39 | \$ -         |

REMARKS:

8 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)