

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 29 January 2021 10:39 AM
To: SUR; Edwin Abcede Caina
Cc: Andre Chow En De; Coco Lu Ting; Don Bong Kiong Hua; Kevin Leong Wai Kit
Subject: SMM 6890K-DOA: 27/1/2021 (AIG OD)

Dear Edwin,

As instructed by our client , please proceed to repair the **insured vehicle SMM 6890K, (Excess \$600).**

(Front LH Rim not consistent, wheel rolled over wooden block) - to remove.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency.

Before paint photos for all NEW Panels and Parts required after repair

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)