

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6
01-48 SPORE 417883

Make Cecilia

Not Authorized

2/5/11 4500/ 28/1/11

3 days.

WOW

VEHICLE No: SKL 7634G

1PC	FRONT BUMPER	De/Torn	1076.45	\$1,515.62 ✓
1PC	FRONT BUMPER CENTRE GARNISH	twi	225.43	\$488.90 ✓
1PC	FRONT BUMPER FOG LAMP GARNISH N/S	SLC		\$105.20 X
1PC	FRONT BUMPER PDC SENSOR N/S	Shohl		\$199.80 ✓
1PC	FRONT BUMPER LICENCE PLATE GARNISH	De	105.00	\$162.00 ✓
1PC	FRONT BUMPER SPONGE	Torn	148.22	\$288.30 ✓
1PC	FRONT BUMPER BEAM	Seat	615.00	\$650.00 ✓
1PC	FRONT BUMPER NOZZLE SPRAY N/S	Cne	258.00	\$399.20 ✓
1PC	FRONT BUMPER SIDE RETAINER N/S	an		\$66.50 X
1SET	FRONT BUMPER CLIPS	nei		\$50.00 ✓
1PC	HEADLAMP N/S	cne	2277.75	\$2,820.00 ✓
1PC	FRONT AIR CON SIDE GARNISH N/S	Torn	92.50	\$97.90 ✓
1PC	FRONT SUPPORT PANEL	R		\$717.00 X
				\$7,560.42

TO CHECK WIRING	\$50.00	30
TO RESET & REPROGRAMME SYSTEM	\$100.00	60
TO DISMANTLE & REPLACED FRT PDC SENSOR	\$80.00	50
TO SPRAY RUST PROOFING	\$50.00	X
TO REFILL AIR CON GAS	\$120.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$680.00	300
TO PUTTY & SPRAY PAINTING	\$800.00	400
		\$9,440.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2045.15

50%

2-4792-89

L-840

5632.81

20%

4506.