

OUR REF:BUS/01/21/7025(AIG) - ACCIDENT ON 22/01/21 INVOLVING SMB1425L AND SFA1778G ALONG Farrer Rd (Bef BS: 41111 – Lutheran Twrs)

Ong Hua Yen (Auto Svcs/FM&SuppSvcs/Claims & IA/Claims & IA)

<OngHuaYen@smrt.com.sg>

Mon 12/7/2021 4:47 PM

To: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Cc: Chong Fei Yuan (Auto Svcs/FM&SuppSvcs/Claims & IA) <FeiYuan@smrt.com.sg>; Balqish Binte Abdul Halil (Auto Svcs/FM&SuppSvcs/Claims & IA/Claims & IA) <BalqishBAH@smrt.com.sg>; Tan Wei Teck (Auto Svcs/FM&SuppSvcs/Claims & IA/Claims & IA) <TanWeiTeck@smrt.com.sg>; Karen Chan Siau Chin (Auto Svcs/FM&SuppSvcs/Claims & IA/Claims & IA) <ChanSiauChin@smrt.com.sg>; Foo Chit Yan (Auto Svcs/FM&SuppSvcs/Claims & IA/Claims & IA) <FooChitYan@smrt.com.sg>

 3 attachments (466 KB)

BUS 01 21 7025 INV.pdf; BUS 01 21 7025 LTA.pdf; BUS 01 21 7025 SAS.pdf;

Dear Sirs,

We claim on behalf of SMRT Buses Ltd, owner of the vehicle registration number SMB1425L. Your client's negligent driving has caused the above accident. As a result, my client has suffered the following losses,

Cost of Repair	\$2,028.00
Loss of Use	\$1,237.50 (4.5 days x \$275.00)
LTA search fee	\$7.00
Total	\$3,272.50

We enclose the following documents,

- 1) 1) Repair Invoice
- 2) 2) GIA report
- 3) LTA Search Fee

We look forward to your confirmation to settle our claims within 15 days from the date of this email. Payment by cheque shall be crossed and made payable to SMRT Buses Ltd.

Thanks & Regards
Hua Yen