



ATAN MOTORING SUPPLY PTE LTD

Blk 3006 Ubi Road 1, #01-368/370 Singapore 408700.
Tel: 67431351 Fax: 67432719 Email: annasimsl@yahoo.com.sg
Business Registration No. A03552/1989W

28 January 2021

AIQ Singapore
Motor Claim Department
78 Shenton Way
#07-16
Singapore 079120

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FBJ7619T (SYM Joyride 200I)

1 pc	Rear Brake Lever	✓	28.00
1 pc	Front Inner Cover	✓	92.00
1 pc	Head Lamp Cover	✓	250.00
1 pc	Left Front Under Cover	✓	98.00
1 pc	Left Under Cover	✓	72.00
1 pc	Front Floorboard	✓	96.00
1 pc	Centre Floorboard	✓	57.00
1 pc	Side Stand Sensor	✓	50.00
1 pc	Side Stand	✓	55.00
1 pc	Main Stand	✓	95.00
1 pc	Rear Box	✓	280.00
	Transport from Idac to Workshop		80.00
	Press Fork		150.00
	Labour		280.00
	Sub total		1683.00
	GST 7%		117.81
	Total		1800.81

1 PC LEFT SIGNAL LIGHT / Cut . 55.00

1228
10% : 1105.2
1495.2
20% : 1150.1200

2 Days.

Unpainted repair

After repair photo

Guo Qiang 8288 0282

01/2/2021