

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0104/2021/KS
DATE : 30-Jan-21
WIP : 13754

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3.2.2021
YOUR INSURED VEH NO :SMH 9386 G

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

8425.44.

Cecilia,

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR YIK YENG WEE
ADDRESS : 6 BROOKVALE WALK
#03-04
SINGAPORE 599954
TELEPHONE : HP +65 97834033
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P90329681DMA
VEHICLE NO : SDT 282 A
MODEL CODE : Q3 2.0 TFSI QU
MODEL YEAR : 30/10/2013
ENGINE NO : CPS 017644
CHASSIS NO : WAUZZZ8U9DR070863
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Jan-21
PLACE OF ACCIDENT : MARINA BOULEVARD, SINGAPORE
JUNCTION TURNING INTO SHEARES AVE

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDT 282 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. S/N \$	360.00 X.	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N \$	400.00 X.	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓	2,400.00 1000	
4	TO RESPRAY FRONT BUMPER, FRONT LOWER SPOILER, LHS FRONT FENDER, BOTH FRONT WHEEL ARCH TRIM AND LHS FRONT DOOR. ✓	4,700.00 2300	3 x 550 = 1650. Spoiler = 250 Wheel Arch : 200 x 2 = 400 <u>2300</u>
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT. S/N \$	280.00 ✓	
6	TO CARRY OUT DIAGNOSTIC CHECK S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 8,332.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDT 282 A

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Dehnd</i>	1	\$ 2,107.00 ✓	1684.40	
2	FRONT BUMPER FIXING PARS <i>net new</i>	1	\$ 109.00 ✗		
3	FRONT BUMPER SPOILER <i>net new</i>	1	\$ 581.00 ✗		
4	FRONT BUMPER TRIM LH <i>net new</i>	1	\$ 24.00 ✗		
5	FRONT BUMPER CLOSING ELEMENT LOWER <i>net new</i>	1	\$ 176.00 ✗		
6	FRONT BUMPER AIR GUIDE GRILLE LH <i>net new</i>	1	\$ 118.00 ✗		
7	FRONT FENDER LH <i>Dehnd</i>	1	\$ 902.00 ✓	721.60	
8	FRONT FENDER ATTACHMENT PARTS LH <i>net new</i>	1	\$ 70.00 ✗		
9	FRONT FENDER BRACKET LH FRONT <i>net new</i>	1	\$ 83.00 ✗		
10	FRONT FENDER BRACE LH <i>net new</i>	1	\$ 105.00 ✗		
11	FRONT WHEEL HOUSING LINER LH <i>net new</i>	1	\$ 240.00 ✗		
12	WHEEL HOUSING LINER ATTACHMENT PARTS LH <i>net new</i>	1	\$ 153.00 ✗		
13	FRONT WHEEL SPOILER LH <i>net new</i>	1	\$ 137.00 ✗		
14	HEADLIGHT MOUNTING LH <i>cracked</i>	1	\$ 118.00 ✗	94.40	
15	HEADLIGHT RETAINER PLATE LH <i>net new</i>	1	\$ 87.00 ✗		
16	HEADLIGHT DISCHARGE LH <i>net new</i>	1	\$ 2,052.00 ✗		
17	HEADLIGHT WASHER CYLINDER LH <i>net new</i>	1	\$ 210.00 ✗		
18	FRONT WHEEL ARCH COVER LH / RH <i>LH cut, RH net new</i>	2	\$ 1,056.00 ✓	844.00	
19	FRONT ALUMINIUM RIM LH <i>cut</i>	1	\$ 1,600.00 ✓	1280.00	
20	SUNDRIES <i>net new</i>		\$ 300.00 ✗	29.04	
TOTAL SPARE PARTS		:	\$ 10,228.00		
TOTAL LABOUR CHARGES		:	\$ 8,332.00		
GRAND TOTAL		:	\$ 18,560.00		

ALL CHARGES ARE INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *03/02/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 06 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: