



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC20012247/Qvf3e2-1 Date: 19/05/2021 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YP 4570P	Veh. Inspected	XD 1698A	
Policy No.	Z20VC05006152	Coverage (\$)	0.00	
Claim No.	20/20/20/VC05/023867	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	02/02/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	ISUZU CYZ52L	c.c	15681	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JALCYZ52L77000095	Colour	WHITE	
Odometer	538314 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/60 R22.5	WEST LAKE	6 mm	
L/H Front Tyre	295/60 R22.5	WEST LAKE	6 mm	
R/H Rear Tyre	295/60 R22.5	WEST LAKE	6 mm	
L/H Rear Tyre	295/60 R22.5	WEST LAKE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/11/2020	Inspection Date	09/11/2020	
Survey held at	NO 29 SUNGEI KADUT STREET 4			
Repairer	ENG HUP ENGINEERING PTE LTD			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	