



CYCLE & CARRIAGE

AG - OD CLAIM
SURVEY: 02/02/21
LICK - STEVE

VEHICLE NO : SMH 441 P

MODEL : MIT/ATRAGE 1.2 CVT

WIP : 62541

Material	:	\$	<u>5,601.10</u>
Labour	:	\$	<u>5,035.00</u>
Sub-Total	:	\$	<u>10,636.10</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>10,336.10</u>
GST 7%	:	\$	<u>723.53</u>
Grand Total	:	\$	<u>11,059.63</u>

Finalise By/Date : LARRY ON 18/02/21

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 10 WORKING DAYS + 4 days (2 wk. ends)

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 02/02/2021	Cust No/Name	KCV10077/TONY WOO QI LUN
	Reg No/Reg Date	SMH441P / 09/01/2019
	Date In/Mileage	02/02/2021/ 33612
	Chassis/Package	MMBSTA13AKH000571 /CS3P
	Engine No	3A92UHL8844
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	18/02/2021/ 15:31	BLD	884 / Lauro Songcuan	62541		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2025.00
RENEW DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER FACE, RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR DAMAGE							
E PNT88000							100.00
REMOVE & INSTALL RADIATOR AND AIRCON CONDENSER TO FACILITATE REPAIR							
A 55900099							80.00
VACUUM & TOP UP AIRCON GAS AND CHECK AIRCON SYSTEM							
E PNT88000							80.00
REMOVE AND INSTALL FRONT BODY KITS							
M SUNDRY							40.00
APPLY BODY SEALANT ON AFFECTED AREAS							
A 54900099							30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
M SUNDRY							40.00
PERFORM RUST PREVENTION ON AFFECTED PORTIONS							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
E PNT98000							2450.00
SPRAY PAINT FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT AIR DAM, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR AND OTHER AFFECTED PORTIONS							
M SUNDRY							20.00
SUNDRIES							
S SPECIALISTJOB							50.00
SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)							
X EXC							-300.00
INSURANCE EXCESS							
X PANEL ASSY,FR END ✓				1.00	1055.00	23.00	812.35
X PANEL,HEADLAMP SUPPORT,UPR ✓				1.00	65.00	23.00	50.05
X PANEL,AIR GUIDE ✓				1.00	112.00	23.00	86.24
X MARK,THREE-DIA ✓				1.00	69.00	23.00	53.13

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 02/02/2021	Cust No/Name	KCV10077/TONY WOO QI LUN
	Reg No/Reg Date	SMH441P / 09/01/2019
	Date In/Mileage	02/02/2021/ 33612
	Chassis/Package	MMBSTA13AKH000571 /CS3P
	Engine No	3A92UHL8844
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/02/2021/ 15:31	BLD	884 / Lauro Songcuan	62541

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X GRILLE,RADIATOR ✓	1.00	554.00	23.00	426.58 ✓
X BRACKET,FR BUMPER,RH ✓	1.00	13.00	23.00	10.01 ✓
X GRILLE,FR UNDER ✓	1.00	165.00	23.00	127.05 ✓
X COVER,HEADLAMP SUPT PANEL ✓	1.00	62.00	23.00	47.74 ✓
X FACE,FR BUMPER ✓	1.00	703.00	23.00	541.31 ✓
X COVER,FR BUMPER ✓	1.00	13.00	23.00	10.01 ✓
X HEADLAMP ASSY,LH ✓	1.00	660.00	23.00	508.20 ✓
X HEADLAMP ASSY,RH ✓	1.00	660.00	23.00	508.20 ✓
X HOOD ✓	1.00	734.00	23.00	565.18 ✓
X INSULATOR,HOOD ✓	1.00	177.00	23.00	136.29 ✓
X CLIP,HOOD INSULATOR ✓	8.00	3.00	23.00	18.48 ✓
X FENDER,FR LH ✓	1.00	497.00	23.00	382.69 ✓
X FENDER,FR RH ✓	1.00	497.00	23.00	382.69 ✓
X EMBLEM ECO ✓	2.00	17.00	00.00	34.00 ✓
X COVER,FR DECK,RH ✓	1.00	16.00	23.00	12.32 ✓
X GARNISH,FR PILLAR,RH ?	1.00	30.00	23.00	23.10 ?
X CONDENSER ASSY,A/C REFRIGE ?	1.00	758.00	23.00	583.66 ?
X PANEL,AIR GUIDE,RH ?	1.00	11.00	23.00	8.47 ?
X PANEL,AIR GUIDE,LH ?	1.00	11.00	23.00	8.47 ?
X LATCH,HOOD ?	1.00	69.00	23.00	53.13 ?
X RIVET,FR BUMPER	6.00	5.00	23.00	23.10 X
X CLIP,FR BUMPER	10.00	4.00	23.00	30.80 X
X DUCT,A/CLNR INTAKE	1.00	131.00	23.00	100.87 X
X TANK,WINDSHIELD WASHER	1.00	74.00	23.00	56.98 X

Z TEXT

AIG - OD CLAIM
 DOA: 02.02.2021
 SURVEY: STEVE (LKK) 02.02.21
 10 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,601.10	Nett	10,336.10
Labour	4,885.00	7% GST on	723.53
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	11,059.63
Diagnostics Job	0.00		
Sundry/Others	-200.00		
Total(w/o GST)	10,336.10		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE


INSURANCE CO. : AIG

Supplementary For Registration No.: SMH 441 P

<u>Material</u>		<u>Cost \$</u>
1	Rivet, FR Bumper (6 pcs)	30.00 / nec
2	Clip, FR Bumper (10 pcs)	40.00 / nec
3	Duct, A/CInr Intake	131.00 / BR
3	Tank, Windshield Washer	74.00 / CRG
		<u>275.00</u>
23% Discount		<u>63.25</u>
		211.75
7% GST		<u>14.82</u>
Total		<u>226.57</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMH 441P

WIP: 62541

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1 /	Condenser Assy A/C Refrige	? / SUPP		✓ RT	} Steve 4/2/21
2 /	Rivet Air Guide LH	? / SUPP		✓ RR	
3 /	Panel Air Guide RH	? / SUPP		✓ RR	
4 /	Latch Hood	? / SUPP		✓ RR	
5 /	Garnish Front Pillar RH	? / SUPP		✓ RR	
6 /	Clip Front Bumper	? / SUPP		✓ RR	}
7 /	Rivet Front Bumper	? / SUPP		✓ RR	
8 /	Air Intake	? / SUPP		✓ RR	
9 /	Washer Tank	? / SUPP		✓ CRU	
10	7	? / SUPP			
11		? / SUPP			
12	7	? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Attraction 1.2

SURVEYOR: Steve @ LK

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	A13A 2019MY

SMH441P
Before use MUT-3 use not to check all the bond

2021.02.16

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	A13A 2019MY

SM14441P

After use scan tool to Base all the data
 2566 Don

2021.02.16

All DTCs

2021.02.16
