

REF: CC3/AG 21001552/ATd3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100365393Claims No. 982951259986Sum Insured: _____ Excess: \$1100

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 441k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFP3193BYr Regn: 2014, Feb.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan c.c. 1395Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 44669 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ28V0E1014142Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm / R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 28/01/21Survey held at PremiumDes. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>09</u>	<u>TP AIG</u>
	<u>Confirm max repair cost \$4221-</u>
	<u>(Red: 3846, 46%)</u>
	<u>MV: 44k</u>
	<u>PV: 33453</u>
	<u>Nett: 10547</u>

Date/Time, File Pass to?

☐: Preli. ReportDays Of Repair: 3

1)

☐: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐: Site Insp (\$ _____)☐: Interview (\$ _____)☐: Tech. Invs (\$ _____)☐: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS: \$1

Photos

Others

Report Format:

Lump Sum / LB.F: 44221

TOTAL

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0074/2021/NS
DATE	:	21-Jan-21
WIP	:	12340

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : YP 6491 X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS LOW POOI FONG
ADDRESS	:	57 HUME AVENUE #09-12 SINGAPORE 598753
TELEPHONE	:	HP +65 97562680
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	2100365393-06
VEHICLE NO	:	SFP 3193 B
MODEL CODE	:	AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR	:	25/2/2014
ENGINE NO	:	CX5 052756
CHASSIS NO	:	WAUZZZ8V0E1014142
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	18-Jan-21
PLACE OF ACCIDENT	:	IN FRONT OF 285A BUKIT BATOK EAST AVE 3



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFP 3193 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO INSTALL SOLAR FILM ON RHS FRONT DOOR WINDOW GLASS.	S/N \$ 400.00	✓ ✓
2	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	S/N \$ 280.00	✓ ✓
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	✗ 250 ✓
4	TO RESPRAY RHS FRONT DOOR, RHS WING MIRROR COVER, RHS FRONT FENDER.	\$ 2,400.00	700 ✓ 550 + 150 = 700
5	TO TOW VEHICLE FROM SCENE OF ACCIDENT.	S/N \$ 280.00	✗
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 4,602.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFP 3193 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 EXTERIOR MIRROR MOUNTING - RH <i>cut</i>		\$ 1,024.00 ✓	819.20
2 MIRROR CAP - RH <i>Reqs</i>		\$ 169.00 +	
3 MIRROR GLASS - RH <i>Missing</i>		\$ 1,687.00 ✓	1349.60
4 FRONT DOOR WINDOW - RH <i>cut</i>		\$ 231.00 ✓	184.40
5 FRONT WINDOW SLOT SEAL - RH <i>cut</i>		\$ 309.00 ✓	246.80
6 CORNER TRIM - RH <i>Not in</i>		\$ 46.00 +	
7 SUNDRIES <i>7</i>		\$ 200.00 ?	X in
TOTAL SPARE PARTS	:	\$ 3,666.00	
TOTAL LABOUR CHARGES	:	\$ 4,602.00	
GRAND TOTAL	:	\$ 8,268.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adnan
: 28/01/21
:
:
:
:
: Not Authorised, 03 Days ✓

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT