

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Abu Kassim, Noor Mariesa

Date: 09 Feb 2021

**Preliminary Advice**

Vehicle No	: SLF3876X	Accident Date	: 02/02/2021
Make	: AUDI Q3	Policy No.	: 2100480189
Assignment Date	: 02/02/2021	Excess	: S\$1,000.00
Date of Inspection	: 02/02/2021	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,296.00
Revised Amount	:S\$	7,431.00
Check Items (Estimated)	:S\$	1,922.00
Total	:S\$	9,353.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	103,000.00
COE / PARF Rebate	:S\$	64,139.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,861.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :