

Stars Autoworks

160 Sin Ming Drive
#06-21 Sin Ming AutoCity
Singapore 575722
Email: starsautoworks@gmail.com

Not Authorized
1/Sup &
Resurvey After Paint
5days

STARS RENTAL & LEASING

160 Sin Ming Drive
#05-21 Sin Ming Drive
Singapore 575722

ESTIMATE

DATE : 01/02/2021
VEHICLE NO : SKW 5548 C
MAKE/MODEL : Hyundai Elantra
ACC DATE : 29/01/2021

PARTICULAR AMOUNT S\$

LIST ITEMS:		
1	1 FRONT BUMPER	364.80 ✓
2	1 FRONT BUMPER LOWER GRILLE	145.60 X
3	1 FRONT BUMPER FOG LAMP - LH	235.80 ?
4	1 FRONT BUMPER FOG LAMP COVER - LH	65.40 X
5	1 FRONT BUMPER INNER FOAM	79.50 ?
6	1 FRONT BUMPER SIDE RETAINER	45.30 ✓
7	1 FRONT RADIATOR GRILLE	214.80 X
8	1 FRONT HEAD LAMP - LH	364.50 ✓
9	1 FRONT FENDER - LH	238.90 ✓
10	1 FRONT FENDER COWLING - LH	68.70 ✓
11	1 FRONT SHOCKABSORBER - LH	237.00 ?
12	1 FRONT KNUCKLE ARM - LH	318.00 ?
13	1 FRONT KNUCKLE BEARING - LH	119.00 ?
14	1 FRONT KNUCKLE BEARING HUP - LH	160.00 ?
15	1 FRONT LOWER ARM - LH	318.00 ?
16	1 FRONT TIE ROD END - LH	68.00 ?
		3,043.30
Less Discount:		20% 608.66
		2,434.64

SPECIAL NETT ITEMS:		
1	10 FRONT BUMPER CLIP	50.00 ✓
2	5 FRONT RADIATOR GRILLE CLIP	25.00 X
3	10 FRONT FENDER COWLING CLIP	50.00 ✓
4	1 FRONT TYRE - LH	250.00 ?
5	1 FRONT TYRE RIM - LH	450.00 3coin
		825.00

LABOUR CHARGES:		
1	TO CHECK WIRING	50.00 2ol
2	TO TUFF KOTE	250.00 3ol
4	TO FRONT WHEEL ALIGNMENT	60.00 ✓
5	TO REMOVE/REFIX UNDERCARRIAGE (FRONT) - RH	450.00 2ool
6	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS	1,100.00 5ool
7	TO SPRAY PAINTING ON AFFECTED AREA	1,000.00 55ol
		2,910.00



LKK Auto Consultants hence notify the Repairer of the following: GRAND TOTAL: 6,169.64

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: