

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 02.02.2021

Time: 10:46:25

Page: 1 | 2

Ang Asia

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305451566
REGN NO : SHD3442Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 28.07.2016
DATE/TIME IN : 02.02.2021 09:50
ACCIDENT DATE : 29.01.2021

TS

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	1,106.00	20.00	884.80	RY
0002 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	X old damage de
0003 04-01-0103-0658-G	REAR WHEEL CAP RH	1	217.20	20.00	173.76	X old damage cut
0004 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	X ny
0005 04-01-0103-1150-A	REAR BUMPER MAT	1	50.00	20.00	50.00	X ny.

SUB-TOTAL : 1,308.56

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	200 250
0002 L	R/I REVERSE SENSOR	120.00	30

SUB-TOTAL : 720.00

\$560 #
02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: