

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21001598/Gqf3e2	
	8 SHENTON WAY TOWERSINGAPOR	-		Date:	03/06/2021	
	ATTN: CHONG AR	NOLD		Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKG 7258K	Veh. Inspected		SDQ 6666C	
	Policy No.	GA537610	Coverage (\$)		0.00	
	Claim No.	S1M031XF	Excess (\$)		0.00	
	Assign From	CHONG ARNOLD	Assign Date		03/02/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VELLFIRE	c.c		2494	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTNGF3DH408023597	Colour		BLACK	
	Odometer	30734 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/50 R18	TOYO		6 mm	
	L/H Front Tyre	235/50 R18	TOYO		6 mm	
	R/H Rear Tyre	235/50 R18	TOYO		6 mm	
	L/H Rear Tyre	235/50 R18	TOYO		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5. General Information						
	Accident Date	31/01/2021	Inspect Date /	Time	03/02/2021 (03:00 PM)	
	Survey held at	JD MOTORSPORTS PTE LTD	•			
	25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000					
1	Estimate Days of Repair					
5b.		Estimate	Days of Repair			

Report Ref No. CS3/ASM21001598/Gqf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.