

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX7271
TAY THIAM SENG
NO

SINGAPORE
TEL : FAX :
PH : 98774500
ATTN :

Term:

ESTIMATE BILL

Number : EB00005621
Date : 02/02/2021
Case No : AD00011587
Vehicle No : SBT629H
Chassis: KNAFH221395023875
Year of Mfr 2008
Policy No
Model : KIA CERATO

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	REAR BUMPER	1.0	621.00	X 0	621.00
2	REAR BUMPER RETAINER LH	1.0	24.00	X 0	24.00
3	REAR BUMPER REINFORCEMENT	1.0	304.00	X 0	304.00
4	REAR BUMPER CENTER LOWER GARNISH	1.0	102.00	X 0	102.00
List Price - Parts Sub Total					1,051.00
5	REVERSE SENSOR	2.0	280.00	0	560.00
Special Nett Price - Parts Sub Total					560.00
Parts Total					1,611.00
6	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	350.00	0	350.00
7	SPRAY PAINT ON THE AFFECTED AREAS	1.0	300.00	0	300.00
8	ANTI-RUST COATING	1.0	50.00	0	50.00
Labour 1 Sub Total					700.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : TWO THOUSAND FOUR HUNDRED SEVENTY-TWO AND CENTS SEVENTY-SEVEN ONLY			Less Excess		0.00
			SUBTOTAL		2,311.00
			GST 7.00%		161.77
			TOTAL		2,472.77

Date of accident : 02/02/2021 11:50 AM. Place : CTE BEFORE EXIT YCK ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE