

## Hui Zhen (LKK Auto)

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Tuesday, 6 April 2021 3:37 pm  
**To:** Hui Zhen (LKK Auto)  
**Subject:** RE: CTI-TP SMA 5147TSURVEYED BY TAUFIKH

Dear Hui Zhen,

AUDIT CHECK DONE FOR sma5147T, FOUND PARTS LIST ITEM 33 IS DUPLICATE WITH ITEM 31.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Hui Zhen (LKK Auto)  
**Sent:** Tuesday, 6 April, 2021 3:09 PM  
**To:** Simon Ho (LKKAuto)  
**Cc:** Shiau Chan (LKKAuto)  
**Subject:** CTI-TP SMA 5147TSURVEYED BY TAUFIKH

Dear Simon,

For your audit.

Best Regards,

**Hui Zhen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [huizhen@lkkauto.com](mailto:huizhen@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)