



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21001735/Uqd3e2 Date: 11/03/2021 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	GBD 261T
	Policy No.	Z20VC05005046	Coverage (\$)	0.00
	Claim No.	20/21/21/VC05/024199	Excess (\$)	600.00
	Assign From	KENNY LIM	Assign Date	05/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN CABSTAR (M)	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JN1SC2F24Z0855653	Colour	PURPLE
	Odometer	394457 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	OHTSU	6 mm
	L/H Front Tyre	195 R15	OHTSU	6 mm
	R/H Rear Tyre	165 R13 (D)	BEARWAY	6/6 mm
	L/H Rear Tyre	165 R13 (D)	BEARWAY	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND FRONT WINDSCREEN BROKEN. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/02/2021	Inspection Date	05/02/2021
	Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks				
	A)THE MARKET VALUE IS S\$22,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	