

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Wednesday, 17 February 2021 3:14 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: CHINA-TP SLQ 6977K SURVEYED BY KENNETH

Dear Shiau Chan,

AUDIT CHECK DONE FOR SLQ6977K, FOUND NO SUCH PART OF REAR END PANEL INNER AND PARTS PRICES NEED VERIFICATION.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO)
Sent: Monday, 15 February, 2021 11:29 AM
To: Simon Ho (LKKAUTO)
Subject: CHINA-TP SLQ 6977K SURVEYED BY KENNETH

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)