

INSURANCE CO.: AIG

Supplementary For Registration No.: SMG 3041 X

	Labour		Cost \$
1	Repair RH Rear Fender		200.00
2	Spray Paint RH Rear Fender		350.00
			550.00
		7% GST	38.50
		Total	588.50

Thank You.

Yours faithfully CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan Customer Service Cycle & Carriage Pandan Gardens