

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 AUTOBAY, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

09-02-2021

OUR REF NO. SLL 6991U

BKW RENT-A-CAR PTE LTD
120 LOWER DELTA ROAD,
#02-15 CENDEX CENTRE,
SINGAPORE 169208

ESTIMATE BILL FOR VEHICLE NO. SLL 6991U MODEL : TOYOTA CAMRY 2.5A

LIST ITEM

1) FRONT BUMPER		\$ 1,635.00	de	710.20
2) FRONT BUMPER CLIPS	10PCS @\$8.90	\$ 89.00	net	30
3) FRONT BUMPER SIDE ATTACHMENT	2PCS @49.24	\$ 98.48	LH to RH x 111	44.24
4) FRONT BUMPER SIDE GARNISH (LH)		\$ 118.00	? dev	
5) FRONT BUMPER LOWER GRILLE		\$ 546.00	* 7mm	216.40
6) FRONT BUMPER LOWER GRILLE CHROME MOULDING (LH)		\$ 218.00	? int	161
7) FRONT BUMPER LOWER GRILLE CHROME MOULDING TOP		\$ 281.00	X un	
8) FRONT BUMPER SPONGE		\$ 286.00	? dev	
9) FRONT BUMPER REINFORCEMENT		\$ 653.00	X	
10) FRONT BUMPER FOG LAMP (LH)		\$ 337.15	X	
11) FRONT GRILLE		\$ 586.00	X	
12) FRONT GRILLE LOGO		\$ 59.00	X	
13) FRONT GRILLE CLIPS	2PCS @\$8.90	\$ 17.80	X	
14) HEAD LAMP (LH) - dismantle photo		950 \$ 1,232.00	chg	10.50
15) HEAD LAMP CLIPS (LH)	2PCS @\$10.50	\$ 21.00	LH net - RH x un	
16) FRONT FENDER (LH)		\$ 798.00	Rx	
17) FRONT FENDER INNERSHIELD (LH)		\$ 286.00	? AA	150.80
18) FRONT FENDER INNERSHIELD CLIPS (LH)	8PCS @\$8.90	\$ 71.20	? net	20
19) FRONT FENDER EMBLEM 'DUAL VVT-I'		\$ 49.80	net	
20) SUPPORT PANEL		\$ 1,293.00	X	
21) SUPPORT PANEL TOP GARNISH		\$ 317.00	X	
22) SUPPORT PANEL TOP GARNISH CLIPS	9PCS @\$8.90	\$ 80.10	X	
LESS DISCOUNT - 25%		\$ 9,072.53		
		\$ 2,268.13		
		\$ 6,804.40		2751.94 20639.5

1) FRONT BUMPER SENSOR WITH CONTROL UNIT

nn.
~~200~~ 2

1) TO CHECK WIRING SYSTEM

2) TO APPLY UNDER SEALING ON AFFECTED AREAS

3) TO REMOVE/REFIX HEAD LAMP ASSY AND LIGHT SYSTEM

4) TO REMOVE/REFIX AIR-CON CONDENSOR, PIPING SYSTEM AND TOP-UP GAS

5) TO REMOVE/REFIX RADIATOR ASSY AND CONDUCT PRESSURE TEST

6) TO REPLACE NEW PART, CUT, WELD, KNOCK ETC

7) TO RESPRAY ON AFFECTED AREAS

\$	880.00	500 960
		\$ 2,420.00

GRAND TOTAL : \$ 9,224.40

2063.95

१७०

Taufsch 97495749

'wp' w/7/21 @ 1300

3023.95

4/5 Resing after repair

4/592400

тапхана елхантасын

of days

0 7/8 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before lifting

- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Acknowledged by: _____

Acknowledged by Repairer
Signature _____

Signature: _____

Date: